

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070066/UMA3Q2**Date:** 22/10/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220127837
Claimant Vehicle No : SJV903K **Insured Vehicle No :** SJY289J
 Date of Loss: 02/07/2024 Nature of Claim: TP Claim No: 9788491898SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV903K**
 Make & Model: TOYOTA WISH, 1.8 X (A) Engine No: 2ZR0438181
 Reg. Date: 11/01/2010 (Man. Year: 2009) Chassis No: ZGE200013815
 Colour: Black Odometer: 259824 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,603.54	7,578.83	3,024.71	28.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	1,980.00	1,670.00	45.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,253.54	9,558.83	4,694.71	32.94
Approved Total (Overridden) (S\$)		7,600.00		
Nett Amount (S\$)	14,253.54	7,600.00	6,653.54	46.68
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		8,327.25		
Global Sum Settlement (S\$)		8,320.00		

INSPECTION

Date of Assignment: 03/07/2024
 Date Inspected: 03/07/2024 Inspected At: Zoom Autowerks Pte Ltd (HQ)
 15 Kaki Bukit Road 4, #01-53
 Singapore 417808
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -RH	Badly Dented	2,201.00 FL	*2,201.00 FL
2	1		*FRONT DOOR CHECKER	Not Necessary	127.82 FL	*- FL
3	1		*FRONT DOOR GLASS	Not Necessary	481.95 FL	*- FL
4	1		*FRONT DOOR GLASS OUTER MOULDING	Not Necessary	124.10 FL	*- FL
5	2		*FRONT DOOR HINGED	Not Necessary	157.00 FL	*- FL
6	1		*FRONT DOOR INNER TRIM BOARD	Deformed / Torn	780.10 FL	*780.10 FL
7	1		*FRONT DOOR LOCK	Damaged	415.40 FL	*415.40 FL
8	1		*FRONT DOOR OUTER HANDLE	Not Necessary	178.50 FL	*- FL
9	1		*FRONT DOOR OUTER HANDLE INNER PAD	Not Necessary	126.50 FL	*- FL
10	1		*FRONT DOOR REGULATOR	Bent	191.37 FL	*191.37 FL
11	1		*FRONT DOOR REGULATOR MOTOR	Jammed	647.86 FL	*647.86 FL
12	1		*FRONT DOOR RUBBER	Torn	245.35 FL	*245.35 FL
13	1		*FRONT DOOR SIDE MIRROR	Not Necessary	1,065.00 FL	*- FL
14	1		*CENTRE PILLAR	Dented / Bent	655.90 FL	*655.90 FL
15	1		*CENTRE PILLAR INNER GARNISH	Not Necessary	225.00 FL	*- FL
16	1		*ROCKER PANEL	Repair	635.00 FL	*- FL
17	1		*REAR DOOR -RH	Distorted	2,201.00 FL	*2,101.10 FL
18	1		*REAR DOOR CHECKER	Twisted	68.50 FL	*68.50 FL
19	1		*REAR DOOR GLASS OUTER MOULDING	Not Necessary	115.00 FL	*- FL
20	1		*REAR DOOR HINGES	Lower Bent	157.00 FL	*75.00 FL
21	1		*REAR DOOR INNER TRIM BOARD	Deformed / Torn	780.95 FL	*780.95 FL
22	1		*REAR DOOR INNER LOCK	Serviceable	455.18 FL	*- FL
23	1		*REAR DOOR GLASS REGULATOR	Bent	291.37 FL	*291.37 FL
24	1		*REAR DOOR GLASS REGULATOR MOTOR	Jammed	647.86 FL	*647.86 FL
25	1		*REAR DOOR RUBBER	Torn	243.35 FL	*243.35 FL
26	1		*SET FRONT DOOR BLACK TAPE	Necessary	120.00 FS	*60.00 FS
27	1		*ROCKER PANEL SIDE SKIRT	Torn	450.00 FS	*450.00 FS
28	1		*SET REAR DOOR BLACK TAPE	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,908.06	9,915.11
- List Item Discount on L Items 25.00/25.00% (\$)	3,304.52	2,336.28
Total Parts (\$)	10,603.54	7,578.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS ,TRANSFER ALL FITTINGS TO NEW DOOR	New	400.00	100.00
2	TO APPLY UNDERCOATING	New	150.00	80.00
3	PANEL BEATING	New	1,600.00	700.00
4	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	1,100.00
Gross Labour Cost (\$\$)			3,650.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >