

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070067/UMA3Q2

Date: 03/09/2024

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D24MFL0003820
Claimant Vehicle No :	SMH8621J	Insured Vehicle No :	GBM3323G
Date of Loss:	01/07/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0007753

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH8621J		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 S (A)	Engine No:	2ZRR951148
Reg. Date:	12/02/2019 (Man. Year: 2016)	Chassis No:	ZVW508035960
Colour:	Blue	Odometer:	347016 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Tracforce 6 mm	Rear Left Side:	Tracforce 6 mm
Front Right Side:	Tracforce 6 mm	Rear Right Side:	Tracforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,925.12	3,332.77	8,592.35	72.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	720.00	2,490.00	77.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,135.12	4,052.77	11,082.35	73.22
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	15,135.12	3,200.00	11,935.12	78.86
+ GST 9.00/9.00% (S\$)	1,362.16	288.00	1,074.16	78.86
Nett Amount (S\$)	16,497.28	3,488.00	13,009.28	78.86
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		3,815.25		
Global Sum Settlement (S\$)		3,800.00		

INSPECTION

Date of Assignment:	03/07/2024		
Date Inspected:	03/07/2024	Inspected At:	Carsmith Private Limited (HQ) 8 Kaki Bukit Ave 4, #04-35 Premier Singapore 415875
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2024)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH8621J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Torn	1,986.70 FL	*781.20 FL
2	1		*FRONT BUMPER LOGO	Serviceable	275.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	625.00 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT SPONGE	Torn	325.00 FL	*222.60 FL
5	2		*FRONT BUMPER REINFORCEMENT BRACKET	Not Necessary	1,250.00 FL	*- FL
6	1		*FRONT BUMPER RETAINER LH	Not Necessary	110.20 FL	*- FL
7	1		*FRONT BUMPER BRACKET LH	Not Necessary	98.70 FL	*- FL
8	1		*FRONT BUMPER LOWER GRILLE	Torn	585.00 FL	*288.20 FL
9	1		*FRONT BUMPER LAMP LH	Cracked	475.00 FL	*475.00 FL
10	1		*FRONT HEADLAMP LH	Cracked	2,586.70 FL	*2,355.20 FL
11	1		*FRONT HEADLAMP BRACKET LH	Not Necessary	176.00 FL	*- FL
12	1		*FRONT FENDER LH	Repair	786.90 FL	*- FL
13	1		*FRONT FENDER INNER SHIELD LH	Torn	296.70 FL	*281.50 FL
14	1		*FRONT FENDER QUARTER MOULDING O/S	Not Necessary	195.80 FL	*- FL
15	1		*FRONT FENDER QUARTER MOULDING N/S	Not Necessary	195.80 FL	*- FL
16	1		*FRONT SUPPORT PANEL	Not Necessary	1,755.00 FL	*- FL
17	1		*BONNET	Not Necessary	2,765.00 FL	*- FL
18	2		*BONNET HINGE	Not Necessary	270.00 FL	*- FL
19	1		*BONNET LOCK	Not Necessary	755.00 FL	*- FL
20	1		*FRONT NUMBER PLATE	Not Necessary	90.00 FS	*- FS
21	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
22	1		*SET FRONT PANEL TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
23	1		*JOINT SEALANT	Not Necessary	100.00 FS	*- FS
					Sub Total (\$\$)	15,803.50 4,433.70
					- List Item Discount on L Items 25.00/25.00% (\$\$)	3,878.38 1,100.93
					Total Parts (\$\$)	11,925.12 3,332.77

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ALL WIRING AND LIGHTING SYSTEM	New	240.00	20.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	0.00
3	REMOVE AND REFIT FRONT AND REAR LINING ,TRIM AND GARNISH	New	300.00	0.00
4	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,200.00	300.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	400.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (\$\$)			3,210.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >