



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMW 5469Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BONNET	TO REPAIR SEE LABOUR	\$1,228.90	\$0.00
1	HEADLAMP RH	CUT	\$3,674.90	\$3,674.90
1	HEADLAMP LOWER BRACKET RH	CRACKED	\$48.00	\$48.00
1	FRONT BUMPER	BUCKLED	\$1,477.80	\$1,211.90
1	FRONT BUMPER RETAINER RH	DISTORTED	\$21.80	\$21.80
1	FRONT BUMPER RETAINER LH	SERVICEABLE	\$21.80	\$0.00
1	FRONT BUMPER REINFORCEMENT	BENT	\$563.30	\$563.30
1	FRONT BUMPER INNER SPONGE	CRACKED	\$73.00	\$73.00
1	FRONT BUMPER TOP GARNISH RH	TO REPAIR SEE LABOUR	\$521.00	\$0.00
1	FRONT GRILLE	CRACKED	\$712.10	\$712.10
1	FRONT GRILL LOGO (NPA)	NOT NECESSARY	\$0.00	\$0.00
1	FRONT GRILLE CHROME RH	CRACKED	\$363.80	\$251.40
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	\$448.00	\$0.00
1	FRONT FENDER INNER SHIELD RH	SERVICEABLE	\$143.10	\$0.00
10	FRONT FENDER INNER SHIELD CLIPS	NOT NECESSARY	\$100.00	\$0.00
1	FRONT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	\$479.30	\$0.00
1	FRONT BUMPER BRACKET RH	CRACKED	\$45.00	\$45.00
1	FRONT BUMPER LOWER CENTRE GRILLE CHROME	SERVICEABLE	\$303.00	\$0.00
1	FRONT GRILLE CHROME INNER GARNISH RH (ADDITIONAL)	CRACKED	\$55.00	\$55.00
1	FRONT GRILLE BASE (ADDITIONAL)	CRACKED	\$172.00	\$133.70
1	FRONT BUMPER SENSOR RH (ADDITIONAL)	MTG DENTED	\$185.00	\$185.00
1	FRONT RADIATOR COVER (ADDITIONAL)	CRACKED	\$190.00	\$190.00
	<b>LESS 20.00% DISCOUNT</b>		(\$2,165.36)	(\$1,433.02)
			<b>\$8,661.44</b>	<b>\$5,732.08</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
10	FRONT BUMPER CLIPS (SN)	NECESSARY	\$80.00	\$50.00
1	FRONT BUMPER SENSOR (2EYE) (SN)	NOT NECESSARY	\$220.00	\$0.00
1	TOP UP AIRCON GAS (SN)	NOT NECESSARY	\$60.00	\$0.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	COOLANT (SN)	NOT NECESSARY	\$40.00	\$0.00
			\$400.00	\$50.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR TO FACILIATE REPAIR. INCLUSIVE OF THE REPAIR OF BONNET, FRONT BUMPER TOP GARNISH RH, FRONT FENDER RH AND FRONT SUPPORT PANEL ASSY		\$1,200.00	\$500.00
	R&R FRONT BUMPER SENSOR		\$60.00	\$50.00
	R&R RADIATOR & AIRCON CONDENSER	NOT NECESSARY	\$120.00	\$0.00
	TO CHECK & RECONNECT ALL WIRINGS		\$60.00	\$20.00
	TO RUST PROOF AFFECTED AREA	NOT NECESSARY	\$80.00	\$0.00
	TO SPRAY PAINT ON AFFECTED AREAS		\$1,200.00	\$800.00
			\$2,720.00	\$1,370.00
GRAND TOTAL			\$11,781.44	\$7,152.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$5,600.00
Report Ref No: CS/GAI24070069/Kvp3e2				

**KSC**

KENNETH KONG SENG CHEONG