

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070074/EPA3Q2
Date: 28/11/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_04
Claimant Vehicle No : SMX3806S Insured Vehicle No : GBG9558M
Date of Loss: 03/06/2024 Nature of Claim: TP Claim No: MFL2024D0007515

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMX3806S
Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B5570286
Reg. Date: 09/01/2021 (Man. Year: 2019) Chassis No: RU11320248
Colour: Metallic Dark Blue Odometer: 82729 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 5 mm
Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,761.00	858.00	1,903.00	68.92
Miscellaneous Items	13.08	13.08	0.00	0.00
Labour	800.00	250.00	550.00	68.75
Paintwork Labour	1,000.00	400.00	600.00	60.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,574.08	1,521.08	3,053.00	66.75
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	4,574.08	1,200.00	3,374.08	73.77
+ GST 9.00/9.00% (S\$)	411.67	108.00	303.67	73.77
Nett Amount (S\$)	4,985.75	1,308.00	3,677.75	73.77
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		58.25		
Nett Liability (S\$)		1,666.25		

INSPECTION

Date of Assignment: 03/07/2024 Present Location: Century Motors (Singapore) Pte Ltd (HQ)
Date Inspected: 04/07/2024 Inspected At: Century Motors (Singapore) Pte Ltd (HQ)
Estimated Period of Repair: 3.0 days 6 Marsiling Lane,
Singapore 739145

Adjuster: CHEN TSUE YEE Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2024)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX3806S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	420.00 F	*- F
2	1		*BONNET HINGE RH	Not Necessary	40.00 F	*- F
3	1		*BONNET HINGE LH	Not Necessary	40.00 F	*- F
4	1		*BONNET LOCK	Not Necessary	100.00 F	*- F
5	1		*FRT GRILLE	Broken	220.00 F	*220.00 F
6	1		*FRT GRILLE MOULDING (CHROME)	Broken	195.00 F	*195.00 F
7	1		*FRT GRILLE LOGO	Necessary	25.00 F	*25.00 F
8	1		*FRT BUMPER	Broken	220.00 F	*220.00 F
9	1		*FRT BUMPER SIDE RETAINER RH	Broken	15.00 F	*15.00 F
10	1		*FRT BUMPER SIDE RETAINER LH	Broken	15.00 F	*15.00 F
11	1		*FRT BUMPER FOG LAMP COVER RH	Cut	30.00 F	*30.00 F
12	1		*FRT BUMPER FOG LAMP COVER LH	Not Necessary	30.00 F	*- F
13	1		*FRT BUMPER FOG LAMP RH	Not Necessary	205.00 F	*- F
14	1		*FRT BUMPER FOG LAMP LH	Not Necessary	205.00 F	*- F
15	1		*FRT BUMPER LOWER COVER	Broken	60.00 F	*60.00 F
16	1		*FRT BUMPER SPONGE (NPA)	Not Necessary	-	*- F
17	1		*FRT BUMPER REINFORCEMENT	Not Necessary	265.00 F	*- F
18	1		*FRT HEADLAMP BRKT RH	Not Necessary	30.00 F	*- F
19	1		*FRT HEADLAMP BRKT LH	Not Necessary	30.00 F	*- F
20	1		*FRT FENDER RH	Not Necessary	205.00 F	*- F
21	1		*FRT FENDER INNER SHIELD RH	Not Necessary	105.00 F	*- F
22	1		*FRT FENDER WHEELARCH COVER RH	Not Necessary	55.00 F	*- F

F=Franchise part.

Sub Total (S\$)	2,510.00	780.00
+ Margin on L,N Items 10.00/10.00% (S\$)	251.00	78.00
Total Parts (S\$)	2,761.00	858.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	13.08	13.08
Sub Total (\$)			13.08	13.08

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINTING	New	1,000.00	400.00
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	800.00	250.00
Gross Labour Cost (\$)			1,800.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >