

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	SOMPO INSURANCE SINGAPORE PL		Ref:	CS/SMO24070075/Aqp3m4	
	50 RAFFLES PLACE #03-03		Date:	21/08/2024	
	SINGAPORE LAND	TOWER SINGAPORE 048623		SMO	
_	Puller Postingles		Code:		
1.	Policy Particulars :- THIRD PARTY CLAIM Insured Veh. GBJ 3444G Veh. Inspected GBH 8715C				
		GBJ 3444G	Veh. Inspected		
	Policy No. Claim No.	- CMTD2402162/AGC	Coverage Excess	\$0.00	
			+		
	Assign From	GRACE TEO	Assign Date	02/07/2024	
2.	Make & Model	Vehicle	C.C	2002	
		TOYOTA HIACE 1KD2829344		2982	
	Engine No. Chassis No.	JTFHT02P900245844	Year of Reg. Colour	15/10/2018 SILVER	
				IN ORDER	
	Odometer Brakes	113299 KM IN ORDER	Steering General	GOOD	
	Modification(s)		General	GOOD	
	woull cation(s)	RIMS: NIL			
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	195R15	BRIDGESTONE	6	
	L/H Front Tyre	195R15	BRIDGESTONE	6	
	R/H Rear Tyre	195R15	BRIDGESTONE	6	
	L/H Rear Tyre	195R15	BRIDGESTONE	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	29/06/2024	Inspection Date	02/07/2024	
	Survey held at	ey held at INFINITY AUTO 57 PTE LTD - 3020A UBI ROAD 1, #01-33, SINGAPORE 408714			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				