

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24060039/ENP3E2**Date:** 01/08/2024REFERENCE

Insured/Claimant:	MATHUR ANURAG CHANDRA	Policy No:	1800075916
Date of Loss:	07/06/2024	Nature of Claim:	OD Claim No: 0945243717SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC1230B		
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Engine No:	CZD870549
Reg. Date:	26/06/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8U7JR070338
Colour:	White	Odometer:	66868 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$98,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R17	Rear Tyre Size:	235/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,148.00	3,791.20	14,356.80	79.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,852.00	1,702.00	2,150.00	55.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,000.00	5,493.20	16,506.80	75.03
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	21,600.00	5,093.20	16,506.80	76.42
+ GST 9.00/9.00% (S\$)	1,944.00	458.39	1,485.61	76.42
Nett Amount (S\$)	23,544.00	5,551.59	17,992.41	76.42

INSPECTION

Date of Assignment:	13/06/2024	
Date Inspected:	14/06/2024	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Inside Holder Broken	2,544.00 FS	*2,035.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	122.00 FS	*- FS
3	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	384.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	272.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	221.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	479.00 FS	*- FS
7	1		*RADIATOR GRILLE	Broken	1,421.00 FS	*1,136.80 FS
8	1		*RADIATOR GRILLE STRIKER PLATE	Broken	163.00 FS	*130.40 FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	129.00 FS	*- FS
10	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	1,116.00 FS	*- FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM COVER	Not Necessary	82.00 FS	*- FS
12	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	30.00 FS	*- FS
13	2		*FRONT WHEEL COVER - LH / RH	Necessary	612.00 FS	*488.80 FS
14	1		*HEADLIGHT - RH	Not Necessary	9,325.00 FS	*- FS
15	1		*HEADLIGHT RETAINING PLATE - RH	Not Necessary	109.00 FS	*- FS
16	1		*LIFT CYLINDER - RH	Not Necessary	167.00 FS	*- FS
17	1		*LIFT CYLINDER HOSE	Not Necessary	233.00 FS	*- FS
18	1		*HEADLIGHT MOUNTING - RH	Not Necessary	147.00 FS	*- FS
19	1		*HEADLIGHT SUPPORT - RH	Not Necessary	32.00 FS	*- FS
20	1		*FRONT NUMBER PLATE	Not Necessary	60.00 FS	*- FS
21	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 18,148.00 3,791.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
4	TO RESPRAY FRONT BUMPER	New	1,200.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$)			3,852.00	1,702.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >