

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070076/APA3Q2
Date: 14/01/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D18MCV0002873_05
Claimant Vehicle No : GBF6420B Insured Vehicle No : GBE4505J
Date of Loss: 02/07/2024 Nature of Claim: TP Claim No: MCV2024D0007800

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF6420B
Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2678123
Reg. Date: 17/01/2017 (Man. Year: 2016) Chassis No: JTFAT35Y50K207409
Colour: Silver Odometer: 166334 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,201.76	2,742.82	2,458.94	47.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	1,130.00	810.00	41.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,141.76	3,872.82	3,268.94	45.77
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	7,141.76	3,100.00	4,041.76	56.59
+ GST 9.00/9.00% (S\$)	642.76	279.00	363.76	56.59
Nett Amount (S\$)	7,784.52	3,379.00	4,405.52	56.59
+ Car Rental (5.0 x S\$100.00/day + 9.00% GST) (S\$)		545.00		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		4,051.25		

INSPECTION

Date of Assignment: 04/07/2024
Date Inspected: 04/07/2024 Inspected At: Twincar Automotive Pte Ltd (HQ)
2 KAKI BUKIT AVEUNE 2 #01-17
Singapore 417921
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Nov 2024)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF6420B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR END PANEL	Dented	957.90 FL	*495.00 FL
2	1		*REAR END PANEL RH SIDE BRACKET	Bent	279.90 FL	*279.90 FL
3	1		*REAR END PANEL RH SIDE BRACKET STOPPER	Not Necessary	60.70 FL	*- FL
4	1		*REAR EXHAUST PIPE	Repair	675.20 FL	*- FL
5	1		*REAR EXHAUST PIPE GASKET	Not Necessary	28.90 FL	*- FL
6	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	71.40 FL	*- FL
7	1		*REAR NUMBER PLATE BRACKET	Bent	155.10 FL	*155.10 FL
8	2		*REAR NUMBER PLATE LAMP L/R	Not Necessary	255.80 FL	*- FL
9	1		*REAR NUMBER PLATE PANEL	Bent	487.90 FL	*290.00 FL
10	1		*REAR RH TAILLAMP	Not Necessary	396.90 FL	*- FL
11	1		*REAR RH TAILLAMP BRACKET	Bent	271.60 FL	*271.60 FL
12	1		*REAR TAILGATE	Dented	1,185.00 FL	*1,185.00 FL
13	1		*REAR TAILGATE DYNA STICKER	Necessary	48.00 FL	*48.00 FL
14	1		*REAR TAILGATE TOYOTA STICKER	Necessary	135.00 FL	*135.00 FL
15	4		*REAR TAILGATE HINES	Bent (2 PCS ONLY)	395.60 FL	*197.80 FL
16	1		*REAR TAILGATE RH SIDE LOCK	Damaged	279.70 FL	*279.70 FL
17	1		*REAR TAILGATE RH SIDE LOCK STRIKER	Not Necessary	155.10 FL	*- FL
18	1		*REAR NUMBER PLATE	Bent	25.00 FS	*25.00 FS
19	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
20	1		*REAR TAILGATE 70KM STICKER	Necessary	25.00 FS	*15.00 FS
21	4		*SET REAR TAILGATE HINGES PIN	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,369.70	3,577.10
- List Item Discount on L Items 20.00/25.00% (S\$)	1,167.94	834.28
Total Parts (S\$)	5,201.76	2,742.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE REINSTALL ELECTRICAL WIRING HARNESS CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	800.00	500.00
3	TO REMOVE AND CHARGE EXHAUST SILENCER BOX WITH PIPE REALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	100.00	0.00
4	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR RE-CONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	800.00	500.00
5	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	50.00
6	TO REMOVE REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	0.00
Gross Labour Cost (\$\$)			1,940.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >