

ASSIGNMENT

Front: _____ Date: _____

Estin: _____

OD / TP RES / OD RES / EVA / INV / MV

To In Vehicle No: _____

at VO 100 km/s

of _____

Insured: _____

Policy: FW

Claims: FW

Sum Ins Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G BT6420B Yr Regn: 2017, Jan.

Type: M.Car / M.Cycle / Bus / Van / Truck / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.D. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 166334 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT 3SY50 k207409

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C

R: 155R12C

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 04/07/24.

Survey held at Twincar

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>7P M</u>
	<u>COE Expiry :</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No (✓)</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>
	<u>500B.</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 + RS. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Report Form:

Report Form:

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

HOR GIAP TRADING
BLK 575 ANG MO KIO AVE 10 #11-1865
SINGAPORE 560575

Contact : 91445482

TAX INVOICE

Repair Code : CLM16353

Date in : 03/07/2024

Vehicle Num. : GBF6420B

Model : TOYOTA DYNA 150 5MT

Chassis/Eng# : JTFAT35Y50K207409/1KD2678123

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR END PANEL <i>Dented</i>	1	957.90	957.90 <i>455</i>
REAR END PANEL RH SIDE BRACKET <i>Best</i>	1	279.90	279.90 ✓
REAR END PANEL RH SIDE BRACKET STOPPER <i>new</i>	1	60.70	60.70 +
REAR EXHAUST PIPE <i>Repair</i>	1	675.20	675.20 +
REAR EXHAUST PIPE GASKET <i>new</i>	1	28.90	28.90 +
REAR EXHAUST PIPE MOUNTING <i>new</i>	2	35.70	71.40 +
REAR NUMBER PLATE BRACKET <i>Best</i>	1	155.10	155.10 ✓
REAR NUMBER PLATE LAMP L/R <i>new</i>	2	127.90	255.80 +
REAR NUMBER PLATE PANEL <i>Best</i>	1	487.90	487.90 ✓
REAR RH TAILLAMP <i>new</i>	1	396.90	396.90 +
REAR RH TAILLAMP BRACKET <i>Best</i>	1	271.60	271.60 ✓
REAR TAILGATE <i>Dented</i>	1	1185.00	1,185.00 ✓
REAR TAILGATE 'DYNA' STICKER <i>new</i>	1	48.00	48.00 ✓
REAR TAILGATE 'TOYOTA' STICKER <i>new</i>	1	135.00	135.00 ✓
REAR TAILGATE HINGES <i>Best 2 pieces</i>	4	98.90	395.60 <i>197.80</i>
REAR TAILGATE RH SIDE LOCK <i>Best</i>	1	279.70	279.70 ✓
REAR TAILGATE RH SIDE LOCK STRIKER <i>new</i>	1	155.10	155.10 +

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

HOR GIAP TRADING
BLK 575 ANG MO KIO AVE 10 #11-1865
SINGAPORE 560575

Contact : 91445482

TAX INVOICE

Repair Code : CLM16353

Date in : 03/07/2024

Vehicle Num. : GBF6420B

Model : TOYOTA DYNA 150 5MT

Chassis/Eng# : JTFAT35Y50K207409/1KD2678123

Subtotal before discount		5,839.70
Percentage discount 20%		1,167.94
Sub-total 1		4,671.76
REAR NUMBER PLATE <i>Bent</i>	1	25.00 25.00 ✓
REAR REVERSE SENSOR - SET <i>Revised</i>	1	280.00 280.00 200 ✓
REAR TAILGATE '70KM' STICKER <i>new</i>	1	25.00 25.00 15 ✓
REAR TAILGATE HINGES PIN - SET <i>new</i>	4	50.00 200.00 ✓
Subtotal before discount		530.00
Percentage discount 0%		0.00
Sub-total 2		530.00
Parts-total		5,201.76

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	1,940.00
Parts & Labour Total	7,141.76

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, etc.
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G
2/s 04/07/24
04 Dyr