



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070078/Kvp3e2
16 RAFFLES QUAY	Date:	03/07/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 2380D	Veh. Inspected	PC 1439G
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005821MFCT	Excess	\$0.00
Assign From	BETTY WONG	Assign Date	03/07/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE (A)	C.C	2982
Engine No.	1KD2197717	Year of Reg.	24/07/2012
Chassis No.	JTFST22PX00013903	Colour	WHITE
Odometer	262217 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15X8	ROAD X	9
L/H Front Tyre	195R15X8	ROAD X	9
R/H Rear Tyre	195R15X8	BRIDGESTONE	6
L/H Rear Tyre	195R15X8	BRIDGESTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/07/2024	Inspection Date	04/07/2024
Survey held at	H C AUTO PTE LTD 160 SIN MING DRIVE #05-09 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days