



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 24013-03/MY / 2024

Date of Report : 8 Apr 2024

AL Autorent Pte Ltd  
C/o No. 1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@Kaki Bukit  
Singapore 417883

### THIRD PARTY SURVEY

ACCIDENT HAPPENED ON 13 Mar 2024

Workshop Address : Bluwel Automotive Service Pte Ltd  
No.1 Kaki Bukit Ave 6  
#01-53/55 AutoBay@ Kaki Bukit  
Singapore 417883

As per your instruction dated 14 Mar 2024 with regard to the above matter. We have carried out a physical inspection on the said vehicle SKW 6975 X . We enclosed herewith our report and findings as follows:

#### 1. VEHICLE PARTICULARS

Registration No	: SKW 6975 X	Engine No	: 1ZRY212209
Model	: Toyota Altis	Mileage	: 361678
Year / Capacity	: 2015/1598	Colour	: Silver
Chassis No	: MR053REH104539062		

#### 2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 205/55 R16	Ecorun	5.00	mm	Sport
REAR O/S	: 205/55 R16	Ecorun	5.00	mm	Sport
FRONT N/S	: 205/55 R16	Ecorun	5.00	mm	Sport
REAR N/S	: 205/55 R16	Ecorun	5.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the n/s front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 6 working days to complete.
5. Enclosed number of photograph : 91 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

#### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SKW 6975 X**  
 Report No: **TP/ 24013-03/MY / 2024**

**SPARE PARTS**

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front headlamp	Damage	\$ 2499.25	\$ 2499.25 /
1	Front grille	Damage	\$ 571.10	\$ 571.10 /
1	Front bumper	Damage	\$ 487.10	\$ 487.10 /
1	Front bumper clip (1 set)	Necessary	\$ 44.00	\$ 44.00 30 /
1	Front bumper fog lamp	Damage	\$ 298.60	\$ 298.60 /
1	Front bumper fog lamp cover	Damage	\$ 172.12	\$ 172.12 /
1	Front bumper reinforcement	Intact	\$ 399.50	\$
1	Front bumper side retainer	Damage	\$ 85.50	\$ 85.50 /
1	Front fender	Damage	\$ 781.90	\$ 781.90 /
1	Front fender inner panel	Repair	\$ 971.10	\$
1	Front fender inner shield	Damage	\$ 372.15	\$ 372.15 281 /
1	Front support panel	Repair	\$ 971.80	\$
1	Front brace panel	Repair	\$ 171.45	\$
1	Front fender 'VVTI' emblem	Necessary	\$ 121.35	\$ 121.35 /
1	Air chamber	Damage	\$ 971.80	\$ 971.80 381 /
1	Front sport rim (original)	Damage	\$ 2010.10	\$ 2010.10 600 /
1	Front wheel hub	Damage	\$ 318.25	\$ 318.25 x nn
1	Front wheel bearing	Damage	\$ 271.10	\$ 271.10 /
1	Front ball joint	Damage	\$ 290.10	\$ 290.10 x nn
1	Front shock absorber	Damage	\$ 581.90	\$ 581.90 457 /
1	Front knuckle arm	Damage	\$ 571.10	\$ 571.10 x nn
			<u>\$ 12961.27</u>	<u>\$ 10447.42</u>
Discount		25.0%	\$ 3240.32	\$ 2611.86
			<u>\$ 9720.95</u>	<u>\$ 7835.56</u>
<u>Special Nett Items</u>				
1	Front fender inner shield clip (1 set)	Damage	\$ 24.00	\$ 24.00 15
1	Front tyre (Depreciation)	Damage	\$ 380.00	\$ 190.00 x nn
			<u>\$ 404.00</u>	<u>\$ 214.00</u>

**Spare Parts Total**      \$ 10124.95      \$ 8049.56

Vehicle No: **SKW 6975 X**  
Report No: **TP/ 24013-03/MY / 2024**


**LABOUR COST**

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 10124.95	\$ 8049.56
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 60.00	\$ 40.00 30
2	To remove and refit front undercarriage.	\$ 380.00	\$ 250.00 200
3	To check and re-adjust (Computerized) all wheel alignment.	\$ 180.00	\$ 120.00 80
4	To remove and refit air-con system, refill gas and test for leakages.	\$ 180.00	\$ 120.00 x
5	To remove and refit radiator system.	\$ 120.00	\$ 60.00 x
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 900.00	\$ 750.00 600
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 900.00	\$ 750.00 600
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 110.00	\$ 60.00 30
Total		\$ 12954.95	\$ 10199.56

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ **8200.00**

SDLS: EIGHT THOUSAND TWO HUNDRED ONLY

  
Qualified Appraiser