



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMF 8957B

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	DEFORMED	\$1,088.20	\$1,088.20
2	REAR BUMPER SIDE RETAINER @\$62.40	NOT NECESSARY	\$124.80	\$0.00
2	REAR BUMPER REFLECTOR @\$110.00	N/S CRACKED	\$220.00	\$110.00
1	REAR BUMPER REINFORCEMENT	DENTED	\$620.00	\$538.00
2	REAR BUMPER TOWING COVER @\$85.00	N/S MISSING	\$170.00	\$43.00
1	REAR BUMPER CENTRE HOLDER	DEFORMED	\$80.00	\$20.00
1	REAR BUMPER EXHAUST PIPE COVER	MISSING	\$130.00	\$130.00
2	REAR TAILLAMP @\$930.00	NOT NECESSARY	\$1,860.00	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$620.00	\$0.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	\$220.00	\$0.00
	LESS 20.00% DISCOUNT		(\$1,026.60)	(\$385.84)
			\$4,106.40	\$1,543.36
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	\$20.00	\$20.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	\$20.00	\$0.00
1	REAR END PANEL INSULATION SEALANT (SN)	NOT NECESSARY	\$120.00	\$0.00
1	REVERSE SENSOR (SN)	DAMAGED	\$220.00	\$200.00
			\$380.00	\$220.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL		\$1,000.00	\$300.00
	TO SPRAY PAINT AFFECTED AREA		\$1,000.00	\$600.00
	TUFF COAT		\$200.00	\$30.00
	WIRING CHECK	NOT NECESSARY	\$80.00	\$0.00
	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	NOT NECESSARY	\$280.00	\$0.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING		\$100.00	\$50.00
			\$2,660.00	\$980.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

GRAND TOTAL		\$7,146.40	\$2,743.36
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$2,200.00
Report Ref No: CS/INC24070085/Aqh3			

TOTAL FOR SPARE PARTS: \$ 4,486.40 \$ 1,763.36
TOTAL FOR LABOUR : \$ 2,660.00 \$ 980.00
TOTAL REPAIR COST: \$ 7,146.40 \$ 2,743.36

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.