

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2400481
INV Date : 03-09-2024

Reference CD/FCI24070086/Uma3
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBL 6863A
Insured Veh. SHA 5995X
Claim No. D24005738MFCT / CTPL/TPD 2
Policy No. D-24101861MFCT
Accident Date 28/06/2024
Inspection Date 04/07/2024

Description	Amount
Third Party Express Settlement	350.00
Sub-Total	350.00
GST (9%)	31.50
Grand Total	381.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CD/FCI24070086/Uma3
16 RAFFLES QUAY	Date:	03/09/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHA 5995X	Veh. Inspected	GBL 6863A
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005738MFCT / CTPL/TPD 2	Excess	\$0.00
Assign From	KAREN TAN	Assign Date	03/07/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE	C.C	2982
Engine No.	1KDB075152	Year of Reg.	14/02/2022
Chassis No.	JTFHT02P000251967	Colour	ORANGE
Odometer	105351 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	AUSTONE	6
L/H Front Tyre	195R15	AUSTONE	6
R/H Rear Tyre	195R15	AUSTONE	6
L/H Rear Tyre	195R15	AUSTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/06/2024	Inspection Date	04/07/2024
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBL 6863A

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TAILGATE	DENTED / BENT	\$2,159.30	\$2,159.30
1	REAR TAILGATE INNER LOCK	SERVICEABLE	\$399.20	\$0.00
1	REAR TAILGATE WEATHERSTRIP	TWISTED	\$388.50	\$388.50
1	REAR TAILGATE TOYOTA MOTIF	SERVICEABLE	\$70.50	\$0.00
1	REAR TAILGATE WINDSCREEN GLASS	NOT NECESSARY	\$1,102.30	\$0.00
1	REAR BUMPER	DISTORTED	\$681.40	\$681.40
1	REAR END PANEL OUTER	DENTED / BENT	\$665.20	\$665.20
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	\$795.40	\$0.00
	LESS 0.00 / 25.00% DISCOUNT		\$0.00	(\$973.60)
			\$6,261.80	\$2,920.80

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TAILGATE 70KM/H STICKER (SN)	NECESSARY	\$15.00	\$10.00
1	REAR TAILGATE 8PAX STICKER (SN)	NECESSARY	\$15.00	\$10.00
1	REAR TAILGATE WINDSCREEN GLASS SEALANT (SN)	NECESSARY	\$40.00	\$40.00
1	SETR REAR BUMPER CLIPS (SN)	NECESSARY	\$65.00	\$30.00
1	REAR BUMPER REVERSE SENSOR (SN)	MALFUNCTION	\$220.00	\$200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	\$50.00	\$30.00
1	REAR CORPORATE ADVERTISEMENT & ARTWORK (SN)	NECESSARY	\$400.00	\$200.00
			\$805.00	\$520.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE AND REPLACED REAR BUMPER REVERSE SENSOR		\$80.00	\$30.00
	REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS		\$120.00	\$100.00
	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM		\$100.00	\$50.00
	LABOR FOR PANEL BEATING, CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS.INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER.		\$800.00	\$600.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS		\$600.00	\$500.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA		\$80.00	\$50.00
			\$1,780.00	\$1,330.00
GRAND TOTAL			\$8,846.80	\$4,770.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$3,800.00
Report Ref No: CD/FCI24070086/Uma3				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

INSPECTION PHOTOS (Page 14 of 14)

PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A



PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : GBL 6863A

