



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JTV 2425

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FORK TUBE ASSY - L/H	SERVICEABLE	980.00	-
1	FORK TUBE ASSY - R/H	SERVICEABLE	980.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	480.00	-
1	FRONT RIM	NOT NECESSARY	750.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	145.00	-
1	FRONT RIM BEARING	NOT NECESSARY	90.00	-
1	HEADLAMP ASSY	CRACKED	1,180.00	900.00
1	HEADLAMP COVER BLACK	CUT	245.00	200.00
1	LAMPSTAY	TO REPAIR SEE LABOUR	485.00	-
1	HANDLE-BAR - L/R/H	SERVICEABLE	522.00	-
1	HAND GRIP	SERVICEABLE	108.00	-
1	HANDLE BAR END	CUT	160.00	50.00
2	MIRROR - L/R/H	O/S CUT	420.00	110.00
1	SET FRONT SIGNAL	CUT	180.00	110.00
1	BRAKE LEVER	CUT	160.00	105.00
1	BRAKE PEDAL	CUT	220.00	160.00
1	FRONT FOOTREST - R/H	CUT	230.00	148.00
1	FRONT FOOTREST BRACKET - R/H	NOT NECESSARY	380.00	-
1	REAR FOOTREST - R/H	CUT	200.00	148.00
1	REAR FOOTREST BRACKET - R/H	NOT NECESSARY	250.00	-
1	EXHAUST PIPE	CUT	2,200.00	1,500.00
2	REAR RIM	SERVICEABLE	880.00	-
1	REAR RIM SHAFT	SERVICEABLE	165.00	-
1	REAR BRAKE DISC	NOT NECESSARY	320.00	-
1	REAR SWING ARM COVER (KIV)	BROKEN	980.00	-
1	SET FAIRING ASSY	CUT / CRACKED	2,800.00	980.00
	LESS 10% DISCOUNT		-1,551.00	-441.10
			13,959.00	3,969.90

Report Ref No. CS/INC24070087/Uqh3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	FRONT NECESSARY	38.00	10.00
2	FORK OILS (SN)	NOT NECESSARY	48.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	100.00	-
1	BEARING CONE (SN)	NOT NECESSARY	120.00	-
			306.00	10.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO RE-ALIGNMENT BODY FRAME.	NOT NECESSARY	550.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF LAMPSTAY.		480.00	300.00
			1,110.00	300.00
	GRAND TOTAL		15,375.00	4,279.90

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,000.00
---	--	--	-----------------

Report Ref No. CS/INC24070087/Uqh3e2(N)

TOTAL FOR SPARE PARTS: \$ 14,265.00 \$ 3,979.90

TOTAL FOR LABOUR : \$ 1,110.00 \$ 300.00

TOTAL REPAIR COST: \$ 15,375.00 \$ 4,279.90

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.