

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| DAMAGE ASSESSMENT REPORT | | | | | |
|------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|----------------|-------|--------------------------|
| | INCOME INSURAN | ICE LTD | | Ref: | CS/INC24070087/Uqh3e2(N) |
| | 75 BRAS BASAH R INCOME CENTRES | ROAD SINGAPORE 189557 | | Date: | 16/04/2025 |
| | ATTN: RAJESWAR | ΥY | | Code: | INC |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SLB 5847M | Veh. Inspected | k | JTV 2425 |
| | Policy No. | | Coverage (\$) | | 0.00 |
| | Claim No. | MT/1284047-002 | Excess (\$) | | 0.00 |
| | Assign From | RAJESWARY D/O DORAISAMY | Assign Date | | 04/07/2024 |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | YAMAHA YZF-R25 | c.c | | 250 |
| | Engine No. | HIDDEN | Year of Reg. | | 2020 |
| | Chassis No. | PMYRG1520K0001934 | Colour | | RED |
| | Odometer | 34779 KM | Steering | | IN ORDER |
| | Brakes | IN ORDER | Modification | | SPORTS RIM |
| | General | GOOD | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance |
| | R/H Front Tyre | 110/70-17 | PIRELLI | | 5 mm |
| | L/H Front Tyre | | | | mm |
| | R/H Rear Tyre | 140/70-17 | PIRELLI | | 5 mm |
| | L/H Rear Tyre | | | | mm |
| 4. | Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION AND O/S BODY. | | | | |
| | DAMAGES SEE DETAILS. | | | | |
| 5. | General Information | | | | |
| | Accident Date | 29/06/2024 | Inspect Date / | Time | 04/07/2024 (10:58 AM) |
| | Survey held at | EROFIA MOTOR TRADING PTE LTD | | | |
| | | 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883 | | | |
| 5a. | Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. | Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days | | | | |
| | | | | | |