

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070089/UUA3Q2**Date:** 18/07/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700007952
Claimant Vehicle No : FBF9488L **Insured Vehicle No :** SLN1991S
 Date of Loss: 24/06/2024 Nature of Claim: TP Claim No: 8445540809SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBF9488L**
 Make & Model: YAMAHA T135, 135cc Engine No: 5YP303521
 Reg. Date: 06/02/2012 (Man. Year: 2011) Chassis No: 5YP303521
 Colour: White Odometer: 7004 km
 Engine Capacity: 135 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70-80-17 Rear Tyre Size: 70-80-17
 Front Left Side: Maxxis 5 mm Rear Left Side: Maxxis 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,359.40	3,497.40	3,862.00	52.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,020.00	300.00	720.00	70.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,379.40	3,797.40	4,582.00	54.68
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	8,379.40	3,000.00	5,379.40	64.20
+ Loss of Use (5.0 x S\$30.00/day) (S\$)		150.00		
(S\$)		3,150.00		
Liabe Amount (50.00%) (S\$)		1,575.00		
+ Other Costs (S\$)		70.00		
Nett Liability (S\$)		1,645.00		

INSPECTION

Date of Assignment: 04/07/2024
 Date Inspected: 04/07/2024 Inspected At: Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Not Necessary	640.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Not Necessary	220.00 FL	*- FL
3	1		*HANDLE -BAR	Bent	188.00 FL	*188.00 FL
4	1		*HANDLE -BAR INNER BRACKET	Serviceable	168.00 FL	*- FL
5	1		*SET HANDLE -BAR END	Not Necessary	120.00 FL	*- FL
6	1		*SET HAND GRIP	Not Necessary	75.00 FL	*- FL
7	1		*HEADLAMP	Cracked	380.00 FL	*380.00 FL
8	1		*SET SIDE MIRROR	Cut	110.00 FL	*80.00 FL
9	1		*CLUTCH LEVER	Cut	95.00 FL	*95.00 FL
10	1		*SET FAIRING ASSY	Cracked	625.00 FL	*550.00 FL
11	1		*FRONT FOOTREST BRACKET	Bent	220.00 FL	*115.00 FL
12	1		*FRONT FOOTREST RUBBERS	N/S Torn	90.00 FL	*40.00 FL
13	1		*GEAR PEDAL	Cut	120.00 FL	*120.00 FL
14	1		*EXHAUST ASSY	Cut	1,800.00 FL	*1,550.00 FL
15	1		*REAR RIM	Not Necessary	580.00 FL	*- FL
16	1		*REAR RIM SHAFT	Not Necessary	125.00 FL	*- FL
17	1		*REAR SWING ARM	Not Necessary	685.00 FL	*- FL
18	1		*REAR FENDER	Cut	285.00 FL	*160.00 FL
19	1		*REAR FOOTRESTS	N/S Cut	160.00 FL	*60.00 FL
20	1		*REAR FOOTREST BRACKETS	N/S Cut	320.00 FL	*148.00 FL
21	1		*SET NUMBER PLATE	Bent	38.00 FS	*20.00 FS
22	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
23	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
24	1		*SET STEERING CONE	Not Necessary	150.00 FS	*- FS
25	1		*STICKER	Necessary	120.00 FS	*60.00 FS
26	1		*REAR BOX	Cut	480.00 FS	*280.00 FS
27	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,060.00	3,846.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	700.60	348.60
Total Parts (\$\$)	7,359.40	3,497.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO REPAIR BODY FRAME	New	520.00	0.00
3	TO PROVIDE LABOUR	New	420.00	300.00
Gross Labour Cost (\$\$)			1,020.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >