

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24070092/KQP3M4**Date:** 08/11/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001059397
Claimant Vehicle No :	SBK9765K	Insured Vehicle No :	SLR5118A
Date of Loss:	01/07/2024	Nature of Claim:	TP
		Claim No:	365601

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBK9765K		
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	27491031338721
Reg. Date:	31/05/2018 (Man. Year: 2018)	Chassis No:	WDD2050402R381962
Colour:	Metallic Grey	Odometer:	34166 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,954.20	4,855.51	3,098.69	38.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	810.00	1,590.00	66.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,354.20	5,665.51	4,688.69	45.28
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	10,354.20	2,600.00	7,754.20	74.89
+ GST 9.00/9.00% (S\$)	931.88	234.00	697.88	74.89
Nett Amount (S\$)	11,286.08	2,834.00	8,452.08	74.89

INSPECTION

Date of Assignment:	04/07/2024		
Date Inspected:	04/07/2024	Inspected At:	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721
Estimated Period of Repair:	3.0 days		

Adjuster: SHIAU CHAN**Manager:** KENNETH KONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2024)
Parts:	143	MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBK9765K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled/Cracked	1,799.00 FL	*1,636.54 FL
2	2		*FRONT BUMPER SIDE RETAINER	Serviceable	236.00 FL	*- FL
3	1		*FRONT BUMPER SIDE COVER N/S	Missing	239.00 FL	*135.00 FL
4	2		*FRONT BUMPER SENSOR HOLDER N/S	Serviceable	66.00 FL	*- FL
5	1		*FRONT FENDER COWLING N/S	Serviceable	247.00 FL	*- FL
6	1		*HEADLAMP N/S	Cut	4,236.00 FL	*3,396.25 FL
7	1		*HEADLAMP LOWER BRACKET N/S	Cracked	105.00 FL	*105.00 FL
8	1		*FRONT BUMPER PARKING SENSOR N/S	Serviceable	280.00 FS	*- FS
9	1		*FRONT BUMPER PARKING RADAR N/S	Serviceable	1,279.00 FS	*- FS
10	8		*FRONT FENDER COWLING CLIPS N/S	Necessary	44.00 FS	*44.00 FS
11	12		*FRONT BUMPER CLIPS	Necessary	66.00 FS	*66.00 FS
12	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
					Sub Total (S\$)	8,647.00 5,382.79
					- List Item Discount on L Items 10.00/10.00% (S\$)	692.80 527.28
					Total Parts (S\$)	7,954.20 4,855.51

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW ACCIDENT DAMAGED PORTIONS. TO PANEL BEAT, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,200.00	350.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	100.00	20.00
3	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA / PANEL	New	1,000.00	440.00
4	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	0.00
Gross Labour Cost (\$\$)			2,400.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >