



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNN 5935E

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	BROKEN	\$549.30	\$549.30
1	FRONT BUMPER RETAINER LHS	BROKEN	\$103.10	\$103.10
1	FRONT FENDER LHS	DENTED	\$979.20	\$698.00
1	FRONT FENDER EMBLEM LHS	NOT NECESSARY	\$70.20	\$0.00
1	FRONT FENDER INNERSHIELD LHS	NOT NECESSARY	\$553.90	\$0.00
2	RETAINER, FRT FENDER LINER (ADDITIONAL)	NECESSARY	\$33.20	\$33.20
2	CLIP, PIN HOLD (ADDITIONAL)	NECESSARY	\$23.80	\$23.80
	LESS 25.00% DISCOUNT		(\$578.18)	(\$351.85)
			\$1,734.52	\$1,055.55

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT HEADLAMP LHS (SN) (LOCAL REPAIR)	CUT	\$2,298.60	\$50.00
1	FRONT RIM LHS (SN) (LOCAL REPAIR)	CUT	\$2,826.68	\$250.00
1	FRONT BUMPER CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
			\$5,175.28	\$300.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REPAIR, PANEL BEAT & ALIGN - ACCIDENT AREA	NOT NECESSARY	\$500.00	\$400.00
	SPRAY PAINT - FRONT BUMPER & FRONT FENDER LHS		\$500.00	\$400.00
	REMOVE & TRANSFER - FRONT BUMPER COMPONENTS		\$120.00	\$0.00
	ALIGN HEADLAMP & TEST WIRING		\$120.00	\$30.00
	RUST PROOFING		\$80.00	\$20.00
	WHEEL ALIGNMENT		\$80.00	\$80.00
			\$1,400.00	\$930.00

GRAND TOTAL			\$8,309.80	\$2,285.55
--------------------	--	--	-------------------	-------------------

	RECOMMENDED COST OF REPAIRS			\$2,285.55
--	------------------------------------	--	--	-------------------

Report Ref No: CS/FCI24070094/Eqp3e2				
---	--	--	--	--



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

CTY

STEVE CHEN TSUE YEE