

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG124060041/ENP3E2
Date: 10/12/2024REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG23008368
Claimant Vehicle No :	SNJ412B	Insured Vehicle No :	XE4147Z
Date of Loss:	10/06/2024	Nature of Claim:	TP
		Claim No:	CDMCG24001445

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNJ412B		
Make & Model:	TOYOTA LEXUS, 2.5 ES250 4DR SEDAN (AUTO) EXECUTIVE (A)		
Reg. Date:	07/01/2019 (Man. Year: 2018)	Engine No:	A25A0235646
Colour:	Black	Chassis No:	JTHB11B1602002887
Engine Capacity:	2487 cc	Odometer:	92437 km
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R18	Rear Tyre Size:	235/45 R18
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,912.40	12,652.07	31,260.33	71.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,850.00	1,470.00	4,380.00	74.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	49,762.40	14,122.07	35,640.33	71.62
Approved Total (Overridden) (S\$)		9,800.00		
(S\$)	49,762.40	9,800.00	39,962.40	80.31
+ GST 9.00/9.00% (S\$)	4,478.62	882.00	3,596.62	80.31
Nett Amount (S\$)	54,241.02	10,682.00	43,559.02	80.31

INSPECTION

Date of Assignment:	11/06/2024	
Date Inspected:	12/06/2024	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Dec 2024)
Parts:	143	TOYOTA LEXUS 2.5 ES250 4DR SEDAN (AUTO) EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNJ412B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	1,838.40 FL	*- FL
2	1		*FRONT BONNET HINGE RH	Not Necessary	101.20 FL	*- FL
3	1		*FRONT BONNET HINGE LH	Not Necessary	81.20 FL	*- FL
4	1		*FRONT BONNET LOCK	Not Necessary	170.10 FL	*- FL
5	1		*FRONT BUMPER	Repair	1,557.50 FL	*- FL
6	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	141.60 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	103.90 FL	*- FL
8	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	103.90 FL	*- FL
9	1		*FRONT BUMPER INNER SPONGE	Not Necessary	152.50 FL	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	1,359.70 FL	*- FL
11	1		*FRONT BUMPER TOW COVER RH	Not Necessary	73.10 FL	*- FL
12	1		*FRONT BUMPER TOW COVER LH	Not Necessary	73.10 FL	*- FL
13	1		*FRONT BUMPER FOG LAMP GARNISH RH	Not Necessary	302.80 FL	*- FL
14	1		*FRONT BUMPER FOG LAMP GARNISH LH	Not Necessary	302.80 FL	*- FL
15	1		*FRONT BUMPER BRACKET RH	Not Necessary	161.10 FL	*- FL
16	1		*FRONT BUMPER BRACKET LH	Not Necessary	161.10 FL	*- FL
17	1		*FRONT GRILLE ASSEMBLY	Not Necessary	2,262.60 FL	*- FL
18	1		*FRONT GRILLE EMBLEM	Not Necessary	1,177.60 FL	*- FL
19	1		*FRONT HEADLAMP ASSEMBLY RH	Deep Scratched	6,191.60 FL	*6,191.60 FL
20	1		*FRONT HEADLAMP ASSEMBLY LH	Not Necessary	6,191.60 FL	*- FL
21	1		*FRONT SUPPORT PANEL	Not Necessary	1,924.00 FL	*- FL
22	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	247.50 FL	*- FL
23	1		*AIRCON CONDENSER	Not Necessary	2,726.00 FL	*- FL
24	1		*RADIATOR	Not Necessary	3,148.80 FL	*- FL
25	1		*FRONT FENDER RH	Dented	2,416.50 FL	*2,416.50 FL
26	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	717.00 FL	*- FL
27	1		*FRONT WHEEL RIM RH	Cut	4,268.20 FN	*200.00 F
28	1		*FRONT SHOCK ABSORBER RH	Not Necessary	1,013.30 FL	*- FL
29	1		*FRONT LOWER ARM RH	Not Necessary	1,140.40 FL	*- FL
30	1		*FRONT KNUCKLE ARM RH	Not Necessary	1,002.50 FL	*- FL
31	1		*FRONT WHEEL BEARING RH	Not Necessary	830.20 FL	*- FL
32	1		*FRONT DOOR SIDE MIRROR ASSEMBLY RH	Broken	2,150.40 FL	*2,150.40 FL
33	1		*FRONT DOOR ASSEMBLY RH	Broken	3,043.80 FL	*3,043.80 FL
34	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS
35	1		*SET FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*SET FRONT GRILLE ASSEMBLY CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*SET FRONT HEADLAMP CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
39	1		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*SET FRONT DOOR INNER TRIM BOARD RH CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
42	1		*FRONT BONNET SEALANT	Not Necessary	150.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	150.00 FS	*- FS
44	1		*FRONT FENDER RH SEALANT	Not Necessary	150.00 FS	*- FS
45	1		*FRONT DOOR RH SEALANT	Necessary	150.00 FS	*30.00 FS
46	1		*FRONT TYRE RH	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	48,626.00	14,032.30
- List Item Discount on L Items 10.00/10.00% (\$)	4,286.78	1,380.23
- Nett Item Discount on N Items 10.00/0.00% (\$)	426.82	0.00
Total Parts (\$)	43,912.40	12,652.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE & REFIX PARTS	New	2,000.00	500.00
2	TO SPRAY PAINT AFFECTED AREAS	New	1,800.00	700.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO TRANSFER FRONT DOOR RH MECHANISM	New	150.00	50.00
5	TO REMOVE & REFIX AIRCON CONDENSER AND TOP UP GAS	New	150.00	0.00
6	TO REMOVE & REFIX RADIATOR AND PRESSURE TEST	New	150.00	0.00
7	TO REMOVE & REFIX FRONT UNDERCARRIAGE	New	500.00	0.00
8	TO REMOVE & REFIX FRONT TYRE AND CONDUCT WHEEL BALANCING	New	150.00	0.00
9	TO CONDUCT FOUR WHEEL ALIGNMENT	New	150.00	80.00
10	TO APPLY ANTI RUST ON AFFECTED PARTS	New	120.00	30.00
11	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
12	TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT. PROGRAMMING & CALIBRATION	New	480.00	80.00
Gross Labour Cost (S\$)			5,850.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >