



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNP 2595L

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT LH FENDER (N)	BENT	\$780.00	\$780.00
1	FRONT LH FENDER PROTECTOR (N)	DENTED/CUT	\$480.00	\$302.00
1	FRONT LH SPORT RIM (N)	DENTED	\$985.00	\$985.00
1	FRONT LH KNUCKLE ARM (N)	BENT	\$695.00	\$695.00
1	FRONT LH WHEEL BEARING (N)	NECESSARY	\$390.00	\$319.00
1	FRONT LH LOWER ARM (N)	SERVICEABLE	\$420.00	\$0.00
1	FRONT LH ABSORBER (N)	BENT	\$455.00	\$455.00
1	FRONT LH DOOR (N)	BENT	\$1,250.00	\$1,250.00
1	FRONT LH DOOR PROTECTOR (N)	DENTED	\$425.00	\$285.00
1	FRONT LH DOOR GLASS FIRM GARNISH (N)	NECESSARY	\$285.00	\$285.00
1	FRONT LH DOOR GLASS FIRM TOP GARNISH (N)	NECESSARY	\$280.00	\$196.00
1	FRONT LH DOOR LOWER HINGE (N)	TO REPAIR SEE LABOUR	\$185.00	\$0.00
1	FRONT LH DOOR INNER RUBBER (N)	SERVICEABLE	\$280.00	\$0.00
1	FRONT LH DOOR INNER LOCK (N)	TO REPAIR SEE LABOUR	\$495.00	\$0.00
1	REAR LH DOOR (N)	BENT	\$1,200.00	\$1,200.00
1	REAR LH DOOR PROTECTOR (N)	DENTED	\$425.00	\$285.00
1	REAR LH DOOR GLASS FIRM GARNISH (N)	NECESSARY	\$285.00	\$285.00
1	REAR LH DOOR GLASS FIRM TOP GARNISH (N)	NECESSARY	\$280.00	\$196.00
1	REAR LH DOOR LOWER HINGE (N)	TO REPAIR SEE LABOUR	\$180.00	\$0.00
1	REAR LH DOOR INNER RUBBER (N)	SERVICEABLE	\$275.00	\$0.00
1	REAR LH DOOR INNER LOCK (N)	TO REPAIR SEE LABOUR	\$450.00	\$0.00
1	REAR LH FENDER (N)	TO REPAIR SEE LABOUR	\$1,850.00	\$0.00
1	REAR LH FENDER PROTECTOR (N)	MISSING	\$480.00	\$312.00
1	REAR LH SPORT RIM (N)	DENTED	\$985.00	\$985.00
1	REAR LH KNUCKLE ARM (N)	BENT	\$650.00	\$650.00
1	REAR LH WHEEL BEARING (N)	NECESSARY	\$390.00	\$312.00
1	REAR LH LOWER ARM (N)	SERVICEABLE	\$395.00	\$0.00
1	REAR LH ABSORBER (N)	SERVICEABLE	\$420.00	\$0.00
1	REAR BUMPER (N)	TO REPAIR SEE LABOUR	\$1,350.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER DIFFUSER (N)	DENTED/CUT	\$650.00	\$650.00
	LESS 10.00%		(\$1,767.00)	(\$1,042.70)
			\$15,903.00	\$9,384.30
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	LH SIDE TYRE @\$325.00 (SN)	SERVICEABLE	\$650.00	\$0.00
			\$650.00	\$0.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE & REFIT LH FRONT & REAR UNDERCARRIAGE	NOT NECESSARY	\$480.00	\$280.00
	REMOVE & REFIT REAR LH FENDER GLASS		\$120.00	\$0.00
	REMOVE & REFIT LH DOOR GLASS		\$150.00	\$120.00
	ALIGNMENT		\$160.00	\$80.00
	WIRING		\$100.00	\$20.00
	TUFFKOTE		\$150.00	\$30.00
	SPRAY PAINTING		\$1,600.00	\$900.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT LH DOOR LOWER HINGE, FRONT LH DOOR INNER LOCK, REAR LH DOOR LOWER HINGE, REAR LH DOOR INNER LOCK, REAR LH FENDER AND REAR BUMPER		\$1,600.00	\$700.00
			\$4,360.00	\$2,130.00
GRAND TOTAL			\$20,913.00	\$11,514.30
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$9,200.00
Report Ref No: CS/AGI24070097/Kqp3				

KSC

KENNETH KONG SENG CHEONG