

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24070105/KUA3Q2**Date:** 10/12/2024**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D24MFL0002040
Claimant Vehicle No : SFQ3797D **Insured Vehicle No :** PC9326X
Date of Loss: 01/07/2024 Nature of Claim: TP Claim No: MFL2024D0007696

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFQ3797D**
Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: HRA2420182A
Reg. Date: 30/05/2017 (Man. Year: 2017) Chassis No: SJNFEAJ11U1946771
Colour: Metallic Grey Odometer: 84852 km
Engine Capacity: 1197 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,101.36	3,546.32	3,555.04	50.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,060.00	3,395.00	1,665.00	32.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,161.36	6,941.32	5,220.04	42.92
Approved Total (Overridden) (S\$)		5,550.00		
Nett Amount (S\$)	12,161.36	5,550.00	6,611.36	54.36
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 08/07/2024
Date Inspected: 08/07/2024 Inspected At: Tan Chong Motor Sales Pte Ltd (Toa Payoh)
17 Lorong 8, Toa Payoh
Singapore 319254
Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Dec 2024)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFQ3797D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER SET FRT	Repair	836.40 FN	*- FN
2	1		*FENDER FRONT LH	Bent	761.80 FN	*761.80 FN
3	1		*FENDER FRONT LH	Serviceable	1,359.70 FN	*- FN
4	1		*MOULDING FRT LH LOWER DOOR	Serviceable	381.70 FN	*- FN
5	1		*MOULDING REAR LH LOWER DOOR	Serviceable	191.30 FN	*- FN
6	1		*FENDER COVER FRT LH	Repair	602.30 FN	*- FN
7	1		*FENDER OVER REAR LH GARNISH	Cut	602.30 FN	*602.30 FN
8	1		*PROTECTOR REAR LH	Serviceable	224.90 FN	*- FN
9	1		*DOOR FRONT LH	Bent	1,427.00 FN	*1,427.00 FN
10	1		*TAPE FR DOOR LH	Necessary	36.10 FN	*36.10 FN
11	1		*MOULDING SASH FRT LH DOOR	Serviceable	143.70 FN	*- FN
12	1		*MOULDING DOOR FRT LH	*Check	245.20 FN	*- FN
13	1		*DOOR REAR LH	Warped / Bent	1,569.60 FN	*1,569.60 FN
14	1		*TAPE RR DOOR LH	Necessary	36.10 FN	*36.10 FN
15	1		*MLDG RR DOOR LH	Serviceable	245.20 FN	*- FN
16	1		*MOULDING SASH REAR LH	Serviceable	143.70 FN	*- FN
17	1		*SASH ASSY FR LH	Serviceable	69.70 FN	*- FN
					Sub Total (S\$)	8,876.70 4,432.90
					- Nett Item Discount on N Items 20.00/20.00% (S\$)	1,775.34 886.58
					Total Parts (S\$)	7,101.36 3,546.32

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	New	360.00	80.00
2	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	New	400.00	0.00
3	REPAIR /REPLACE FRT BUMPER ,FRT LH FENDER ,FRT LH DOOR ,REAR LH DOOR AND REAR LH FENDER	New	2,150.00	1,290.00
4	RESPRAY FRT BUMPER ,FRT LH FENDER ,FRT LH DOOR ,REAR LH DOOR AND REAR LH FENDER	New	1,900.00	1,900.00
5	TRANSFER FRT LH AND REAR LH DOOR MECHANISM TO NEW DOOR	New	250.00	125.00
Gross Labour Cost (\$\$)			5,060.00	3,395.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >