9/19/24, 2:43 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24070106/UMA3Q2

Date: 19/09/2024

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900157969 **Claimant Vehicle**

SMZ3279C Insured Vehicle No: SJU6886S No:

Date of Loss: 04/07/2024 Nature of Claim: TP Claim No: 5325694856SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMZ3279C

Make & Model: BMW Z4, 2.0 (A) Engine No: A3960176N20B20A Reg. Date: 13/03/2017 (Man. Year: 2012) Chassis No: WBALL52040E750919

Colour: Multi-colour Odometer: 91704 km

Engine Capacity: 1997 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: Yes Engine Modification: No Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 245/357 R19 Rear Tyre Size: 275/307 R18 Front Left Side: Rear Left Side: Michelin 5 mm Michelin 5 mm Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,117.61	2,161.25	3,956.36	64.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,080.00	2,120.00	1,960.00	48.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,197.61	4,281.25	5,916.36	58.02
Approved Total (Overridden) (S\$)		3,400.00		
Nett Amount (S\$)	10,197.61	3,400.00	6,797.61	66.66
+ Car Rental (4.0 x S\$	150.00/day) (S\$)	600.00		
+ Doc/	Search Fee (S\$)	33.18		
N	ett Liability (S\$)	4,033.18		
Global Sum	Settlement (S\$)	4,000.00		

INSPECTION

Date of Assignment: 08/07/2024

Date Inspected: 08/07/2024 Inspected At: 15 Kaki Bukit Road 4, #01-53

Zoom Autowerks Pte Ltd (HQ)

Singapore 417808

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -LH	Dented / Bent	2,085.00 FL	*2,085.00 FL
2	1		*FRONT DOOR LOCK	Serviceable	155.70 FL	*- FL
3	1		*FRONT DOOR RUBBER	Necessary	241.00 FL	*190.00 FL
4	1		*FRONT DOOR SIDE MIRROR	Not Necessary	155.00 FL	*- FL
5	0		*ROCKER PANEL SIDE SKIRT (NPA)		0.00 FL	-
6	1		*REAR TYRE	Serviceable	500.00 FS	*- FS
7	1		*REAR SPORT RIM -LH	Repair	2,500.00 FS	*- FS
8	1		*ROCKER PANEL SIDE SKIRT	Repair	645.00 FL	*- FL
F=Fra	nchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	6,281.70	2,275.00
			- List Item Discou	nt on L Items 5.00/5.00% (S\$)	164.09	113.75
				Total Parts (S\$)	6,117.61	2,161.25
			Report was unsubmitte	ed during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO CONDUCT WHEEL ALIGNMENT	New	180.00	60.00
2	TO REMOVE,REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS ,TRANSFER ALL FITTINGS TO NEW DOOR	New	200.00	80.00
3	TO APPLY UNDERCOATING	New	100.00	30.00
4	PANEL BEATING	New	1,000.00	350.00
5	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	800.00	600.00
6	TO WRAP FRONT FENDER, DOOR AND REAR FENDER STICKER	New	1,800.00	1,000.00
	Gross Labour Cost (S\$)		4,080.00	2,120.00
	Report was unsubmitted during the	nis print-out.		

< END OF ESTIMATES >