

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24070109/KNP3M4**Date:** 16/07/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003597105
Claimant Vehicle No :	SLT6182X	Insured Vehicle No :	SNF2932A
Date of Loss:	04/07/2024	Nature of Claim:	TP
		Claim No:	365685

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT6182X	Engine No:	G4FGHU620895
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU569199
Reg. Date:	04/11/2017 (Man. Year: 2017)	Odometer:	118006 km
Colour:	Metalic Light Gold		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,680.88	4,426.00	5,254.88	54.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,170.00	1,400.00	1,770.00	55.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,850.88	5,826.00	7,024.88	54.66
Approved Total (Overridden) (S\$)		4,650.00		
(S\$)	12,850.88	4,650.00	8,200.88	63.82
+ GST 9.00/9.00% (S\$)	1,156.58	418.50	738.08	63.82
Nett Amount (S\$)	14,007.46	5,068.50	8,938.96	63.82

INSPECTION

Date of Assignment:	05/07/2024		
Date Inspected:	05/07/2024	Inspected At:	E M SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

According to repairer, they refuse to accept the offer at \$4,000.00 and will pass the case to lawyer.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jul 2024)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT6182X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	1,783.60 FL	*1,783.60 FL
2	1		*REAR BOOT LOGO	Necessary	58.80 FL	*58.80 FL
3	1		*REAR BOOT EMBLEM ELANTRA	Necessary	62.80 FL	*62.80 FL
4	1		*REAR BOOT EMBLEM S	Necessary	48.60 FL	*48.60 FL
5	2		*REAR BOOT LAMPS - L/R	Serviceable	963.20 FL	*- FL
6	1		*REAR BOOT INNER LOCK	Dented	220.60 FL	*116.00 FL
7	1		*REAR BOOT INNER TRIM	Serviceable	311.50 FL	*- FL
8	1		*REAR BOOT W/STRIP (50%) (SN)	Dented/Distorted	181.20 FN	*90.60 F
9	2		*REAR BOOT HINGES - L/R	Repair	323.00 FL	*- FL
10	2		*REAR BOOT STOPPERS	Serviceable	25.20 FL	*- FL
11	1		*REAR BUMPER	Cracked	610.50 FL	*495.60 FL
12	2		*REAR BUMPER REFLECTORS - L/R	Serviceable	179.00 FL	*- FL
13	1		*REAR BUMPER DIFUSSER	Bent	383.90 FL	*383.90 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	481.90 FL	*329.00 FL
15	2		*REAR BUMPER SIDE RETAINERS - L/R	Serviceable	131.00 FL	*- FL
16	1		*REAR END PANEL	Bent	546.80 FL	*546.80 FL
17	1		*REAR END PANEL GARNISH	Mtg Distorted	181.60 FL	*181.60 FL
18	1		*REAR FLOOR BOARD	Serviceable	510.60 FL	*- FL
19	1		*REAR FLOOR PANEL	Repair	860.90 FL	*- FL
20	2		*REAR FENDER INNER TRIMS - L/R	Serviceable	962.40 FL	*- FL
21	1		*REAR SMART KEYLESS ANTENNA	Dented	182.20 FL	*182.20 FL
22	1		*REAR TAILLAMPS - L/R	N/S MtgCracked/O/S Serviceable	1,328.40 FL	*389.40 FL
23	2		*REAR TAILLAMP PANELS - L/R	Repair	391.20 FL	*- FL
24	2		*REAR BUMPER BRACKETS	Cracked	97.20 FL	*97.20 FL
25	1		*SET REAR BOOT INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
26	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
27	1		*SET REAR NO. PLATE	Dented	60.00 FS	*45.00 FS
28	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
29	1		*REAR REVERSE CAMERA	Dented/Shorted	580.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	11,846.10	5,361.10
- List Item Discount on L Items 20.00/20.00% (S\$)	2,128.98	935.10
- Nett Item Discount on N Items 20.00/0.00% (S\$)	36.24	0.00
Total Parts (S\$)	9,680.88	4,426.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE, REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	60.00
3	TO REMOVE, REFIX REAR CAMERA / SENSOR	New	80.00	60.00
4	TO RESPRAY UNDERCOATING	New	120.00	60.00
5	TO RESPRAY PAINTING AND ETC	New	1,200.00	600.00
6	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS	New	1,600.00	600.00
Gross Labour Cost (\$\$)			3,170.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >