

ASS. REC. BY:

REF:

SMR/ CS/SMR24070114/Kvp3

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SHB 5327U

Policy No.

Claims No. TAX/06/24/2063

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 GIA & EA not ready

319 11 Days 81100k. Colour (red 7633.32, 87%)

Veh No:

84N5049H Yr Regn: 04, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MIR Caste (A) c.c. 2998

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

331616

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

12 EC 9114A 00059

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

Amber Stone

R:

Hilo 215/75R17.50

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

00

mm

L/Bal.

9

mm

L/Bal.

00

mm

D.O.A.

24/6/24

D.O.I.

5/7/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s & Frt n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Data/Time, File Pass to?

☐

: Prell. Report

1)

Data/Time, File Return to?

☐

: Final Report

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



5035 Ang Mo Kio Industrial Park 2 #01-373 Singapore 569538
 Company UEN: 53308377W Tel: 9876 5547
 Email: joyskerworks@gmail.com

Not Authored
 11 Pm @ 1100h
 Heavy After Rain
 3 days

ESTIMATE

TO: MS FIRST CAP SURVEY VEHICLE: YN5049H
 ATTENTION: MOTOR CLAIMS DEPARTMENT MAKE/MODEL: MITSUBISHI CANTER
 DATE OF ACCIDENT: 24-06-2024
 CLAIM TYPE: THIRD PARTY CLAIM

No.	LIST ITEM	QTY	UNIT LIST PRICE (\$)	TOTAL LIST PRICE (\$)
1	FRONT HEADLAMP RH <i>CM</i>	1	\$ 501.42	\$ 501.42
2	FRONT SIGNAL LAMP RH <i>CM</i>	1	\$ 266.36	\$ 266.36
3	FRONT HEADLAMP SIDE GARNISH RH <i>R</i>	1	\$ 230.34	\$ 230.34
4	FRONT BUMPER <i>R</i>	1	\$ 1,010.34	\$ 1,010.34
5	FRONT BUMPER BRACKET RH <i>R</i>	1	\$ 169.30	\$ 169.30
SUB TOTAL				\$ 2,177.76
LESS -25%				\$ 544.44
TOTAL				<u>\$ 1,633.32</u>

No.	S/NETT ITEM	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR ALUMINIUM HYD LIFTER PLATFORM TAILGATE ROLLER	1	\$ 280.00	\$ 280.00
2	REAR ALUMINIUM HYD LIFTER PLATFORM TAILGATE TILT	1	\$ 2,800.00	\$ 2,800.00
3	REAR UNDER BAR	1	\$ 600.00	\$ 600.00
4	REAR UNDER BAR REFLECTIVE STICKER SET	1	\$ 150.00	\$ 150.00

\$ 3,830.00

No.	LABOUR		
1	TO DISMANTLE DAMAGE TAILGATE/HYSDAULIC REPAIR	\$ 1,500.00	300
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION AND POLISHING AFFECTED AREA	\$ 600.00	300
3	TO DISMANTLE AND REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 600.00	180
4	TO APPLY ANTI-RUST AND TUFF KOTE	\$ ~ 120.00	X
5	TO PERFROM LIGHTING AND WIRING CHECK	\$ 120.00	20
6	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ ~ 80.00	X
7	TO PERFROM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ ~ 250.00	X

TOTAL \$ 3,270.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: