



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: ASTER QUEK

Ref: CS/INC24070121/Avh3e2(N)

Date: 13/11/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 5592R	Veh. Inspected	SBR 90X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1284641-001	Excess (\$)	0.00
Assign From	SITI RAUDHAH	Assign Date	05/07/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE	c.c	2493
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	AGH300014648	Colour	WHITE
Odometer	135442 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	MICHELIN	6 mm
L/H Front Tyre	235/50 R18	MICHELIN	6 mm
R/H Rear Tyre	235/50 R18	MICHELIN	6 mm
L/H Rear Tyre	235/50 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/07/2024	Inspect Date / Time	05/07/2024 (01:15 PM)
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **13 Working Days**