

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile							
MS	GOLDBELL LEASING PTE LTD		Ref:	CD/GBL24070122/Aua3			
	14 BENOI ROAD S	INGAPORE 629887	Date:	14/08/2024			
			Code:	GBL			
4		Policy Posticulous . D					
1.	Insured Veh.	Policy Particulars :- D	Veh. Inspected	N1 SHD 3415B			
		10 11/11	· ·	0			
	Policy No.	_	Coverage Excess	\$0.00			
	Assign From		Assign Date	05/07/2024			
_	Assign From	- Vahiala	<u> </u>	03/07/2024			
2.	<u> </u>	HYUNDAI I40 1.7 CRDI F/L AT ABS					
	Make & Model	AIRBAG 4DR	C.C	-			
	Engine No.	D4FDGU656073	Year of Reg.	18/08/2016			
	Chassis No.	KMHLB41UMGU093313	Colour	-			
	Odometer	1063739 KM	Steering	IN ORDER			
	Brakes	IN ORDER	General	GOOD			
	Modification(s)	RIMS: NIL					
3.	3. Conditions of Tyres						
		Size	Make	Balance (mm)			
•		Size	mano	` '			
	R/H Front Tyre	205/60 R16	GITI	4			
	R/H Front Tyre L/H Front Tyre			· , ,			
		205/60 R16	GITI	4			
	L/H Front Tyre	205/60 R16 205/60 R16	GITI GITI	4			
4.	L/H Front Tyre R/H Rear Tyre	205/60 R16 205/60 R16 205/60 R16	GITI GITI GITI GITI	4 4 4			
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	205/60 R16 205/60 R16 205/60 R16 205/60 R16	GITI GITI GITI GITI	4 4 4			
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	205/60 R16 205/60 R16 205/60 R16 205/60 R16 Description of the Description of the Descrip	GITI GITI GITI GITI	4 4 4			
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	205/60 R16 205/60 R16 205/60 R16 205/60 R16 Description of the Description of the Descrip	GITI GITI GITI GITI GITI Of Damages	4 4 4			
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	205/60 R16 205/60 R16 205/60 R16 205/60 R16 205/60 R16 Description of the Description of	GITI GITI GITI GITI GITI Of Damages	4 4 4			
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN	205/60 R16 205/60 R16 205/60 R16 205/60 R16 205/60 R16 Description of the Description of	GITI GITI GITI GITI Of Damages formation Inspection Date	4 4 4			
THE	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN AGES SEE DETAIL Accident Date	205/60 R16 205/60 R16 205/60 R16 205/60 R16 Description of the properties of the pr	GITI GITI GITI GITI Of Damages formation Inspection Date PTE LTD	4 4 4			
THE DAN 5. 5a. A)TH	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre E VEHICLE SUSTAIN MAGES SEE DETAIL Accident Date Survey held at	205/60 R16 205/60 R16 205/60 R16 205/60 R16 Description ED DAMAGES AT THE O/S BODY. S. General In 04/07/2024 COMFORTDELGRO ENGINEERING I 59 LOYANG DRIVE	GITI GITI GITI GITI GITI Of Damages formation Inspection Date PTE LTD arks JUDICE" BASIS.	4 4 4 4			
THE DAN 5. 5a. A)TH	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre E VEHICLE SUSTAIN MAGES SEE DETAIL Accident Date Survey held at	205/60 R16 205/60 R16 205/60 R16 205/60 R16 Description of the properties of the pr	GITI GITI GITI GITI GITI Of Damages formation Inspection Date PTE LTD arks JUDICE" BASIS. DT AUTHORISED R	4 4 4 4			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHD 3415B

REPLACEMENT OF PARTS								
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)				
1	REAR DOOR RH	DENTED	\$2,416.80	\$2,416.80				
1	REAR WHEEL CAP RH	NOT NECESSARY	\$217.20	\$0.00				
	LESS 20.00% DISCOUNT		(\$526.80)	(\$483.36)				
			\$2,107.20	\$1,933.44				
	Special Nett							
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)				
1	REAR DOOR ZIG APPS RH (SN)	NECESSARY	\$80.00	\$80.00				
			\$80.00	\$80.00				
	Labour							
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)				
	PANEL BEATING-REAR FENDER ARCH RH ETC		\$700.00	\$300.00				
	SPRAY PAINTING-ROCKER PANEL RH ETC		\$900.00	\$560.00				
	WHEELALIGNMENT	NOT NECESSARY	\$120.00	\$0.00				
			\$1,720.00	\$860.00				
	GRAND TOTAL	\$3,907.20	\$2,873.44					
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$2,300.00					

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

Report Ref No: CD/GBL24070122/Aua3






INSPECTION PHOTOS (Page 1 of 5)
















INSPECTION PHOTOS (Page 2 of 5)








INSPECTION PHOTOS (Page 3 of 5)







INSPECTION PHOTOS (Page 4 of 5)















INSPECTION PHOTOS (Page 5 of 5)













19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)







