

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070123/AUA3Q2
Date: 06/01/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_04
Claimant Vehicle No : SNQ6606H Insured Vehicle No : YP9737T
Date of Loss: 05/07/2024 Nature of Claim: TP Claim No: MFL2024D0008524

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNQ6606H
Make & Model: TOYOTA SIENTA HYBRID, 1.5 X CVT (A) Engine No: M15AY874167
Reg. Date: 30/04/2024 (Man. Year: 2024) Chassis No: MXPL101106637
Colour: Black Odometer: 17087 km
Engine Capacity: 1490 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,812.67	3,169.70	4,642.97	59.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,580.00	1,350.00	46.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,742.67	4,749.70	5,992.97	55.79
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	10,742.67	3,800.00	6,942.67	64.63
+ GST 9.00/9.00% (S\$)	966.84	342.00	624.84	64.63
Nett Amount (S\$)	11,709.51	4,142.00	7,567.51	64.63
+ Loss of Use (1.0 x S\$60.00/day) (S\$)		60.00		
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		4,729.25		
Global Sum Settlement (S\$)		4,720.00		

INSPECTION

Date of Assignment: 05/07/2024
Date Inspected: 05/07/2024 Inspected At: Twincar Automotive Pte Ltd (HQ)
2 KAKI BUKIT AVEUNE 2 #01-17
Singapore 417921
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Nov 2024)
Parts:	M1-MPV	TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNQ6606H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	679.00 FL	*679.00 FL
2	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	103.80 FL	*- FL
3	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	820.00 FL	*410.00 FL
4	4		*REAR BUMPER REVERSE SENSOR O RING	Not Necessary	83.60 FL	*- FL
5	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	109.20 FL	*109.20 FL
6	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	368.20 FL	*- FL
7	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	201.80 FL	*- FL
8	1		*REAR END PANEL INNER	Repair	1,092.40 FL	*- FL
9	1		*REAR END PANEL OUTER	Repair	648.00 FL	*- FL
10	1		*REAR END PANEL ANTENNA SENSOR	Cracked	76.30 FL	*76.30 FL
11	1		*REAR END PANEL INNER TOP GARNISH	Deformed	201.00 FL	*201.00 FL
12	2		*REAR FENDER INNER TRIM BOARD L/R	Not Necessary	1,696.00 FL	*- FL
13	1		*REAR TAILGATE	Dented	1,985.10 FL	*1,395.00 FL
14	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	170.20 FL	*170.20 FL
15	1		*REAR TAILGATE LOGO EMBLEM	Not Necessary	91.80 FL	*- FL
16	2		*REAR TAILGATE HINGES L/R	Not Necessary	166.80 FL	*- FL
17	2		*REAR TAILGATE INNER GUIDE STOPPER L/R	Not Necessary	105.40 FL	*- FL
18	1		*REAR TAILGATE INNER PULL HANDLE	Not Necessary	34.90 FL	*- FL
19	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	87.10 FL	*- FL
20	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	37.40 FL	*- FL
21	1		*REAR TAILGATE MECHANISM LOCK	Damaged	496.00 FL	*496.00 FL
22	1		*REAR TAILGATE WEATHERSTRIP	Cut	456.00 FL	*456.00 FL
23	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	86.90 FL	*86.90 FL
24	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
25	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
26	2		*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Not Necessary	100.00 FS	*- FS
27	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
29	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
30	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	40.00 FS	*- FS
31	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,261.90	4,189.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,449.23	1,019.90
Total Parts (\$\$)	7,812.67	3,169.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	400.00	0.00
2	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PAKRING SENSOR	New	80.00	80.00
3	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
4	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT TRIM GARNISH TRIM LINER CARPET (TO FR)	New	100.00	60.00
5	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
6	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
7	TO APPLY ANTI RUST CHENICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
8	TO REMOVE REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	60.00
Gross Labour Cost (\$\$)			2,930.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >