

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III24070127/UDP3E2
Date: 26/07/2024REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D23MCV0005174_01
Claimant Vehicle No :	SGM79Y	Insured Vehicle No :	PA9687P
Date of Loss:	04/07/2024	Nature of Claim:	TP
		Claim No:	MCV2024D0007754

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGM79Y		
Make & Model:	TOYOTA CAMRY, 2.5 HYBRID ASCENT (A)	Engine No:	A25A5094112
Reg. Date:	14/06/2019 (Man. Year: 2018)	Chassis No:	JTNB23HK803020081
Colour:	Black	Odometer:	108504 km
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45Z R18	Rear Tyre Size:	235/45Z R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,651.85	1,106.30	2,545.55	69.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	780.00	1,950.00	71.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,381.85	1,886.30	4,495.55	70.44
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	6,381.85	1,500.00	4,881.85	76.50

INSPECTION

Date of Assignment:	05/07/2024	
Date Inspected:	08/07/2024	Inspected At: We Garage (HQ) 1 Kaki Bukit Avenue 6, #02-11 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2024)
Parts:	143	TOYOTA CAMRY 2.5 HYBRID ASCENT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGM79Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut / Torn	768.40 FL	*768.40 FL
2	2		*REAR BUMPER SIDE RETAINERS R/L	Not Necessary	137.40 FL	*- FL
3	1		*REAR FENDER (L)	Repair	1,368.70 FL	*- FL
4	1		*REAR FENDER INNER SHIELD	Not Necessary	176.20 FL	*- FL
5	1		*REAR FENDER AIR GATE	Not Necessary	81.50 FL	*- FL
6	1		*REAR WINDSCREEN MOULDING	Not Necessary	121.90 FL	*- FL
7	1		*REAR TAILLAMP (L)	Not Necessary	641.70 FL	*- FL
8	1		*SET REAR BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
9	1		*SET REAR BUMPER CLIPS	Repeated	65.00 FS	*- FS
10	1		*REAR TYRE	Serviceable	250.00 FS	*- FS
11	1		*REAR RIM (LH)	Cut	800.00 FS	*500.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	4,475.80 1,298.40
					- List Item Discount on L Items 25.00/25.00% (\$\$)	823.95 192.10
					Total Parts (\$\$)	3,651.85 1,106.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
3	TO APPLY UNDERCOATING	New	120.00	0.00
4	PANEL BEATING	New	1,000.00	300.00
5	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,200.00	400.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
Gross Labour Cost (\$\$)			2,730.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >