

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG24070133/RNP3M4**Date:** 27/08/2024REFERENCE

Insured/Claimant:	LAM CHUN KIT	Policy No:	1800007682	
Date of Loss:	04/07/2024	Nature of Claim:	OD	Claim No: 7287265546SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW2440L		
Make & Model:	AUDI A3, 999cc SEDAN 1.0 TFSI S TRONIC (LED & NAV) (A)	Engine No:	CHZ601124
Reg. Date:	01/02/2018 (Man. Year: 2017)	Chassis No:	WAUZZZ8V0J1032084
Colour:	Black	Odometer:	107286 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,884.00	16,650.48	13,233.52	44.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,072.00	7,972.00	4,100.00	33.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,956.00	24,622.48	17,333.52	41.31
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	41,356.00	24,022.48	17,333.52	41.91
+ GST 9.00/9.00% (S\$)	3,722.04	2,162.02	1,560.02	41.91
Nett Amount (S\$)	45,078.04	26,184.50	18,893.54	41.91

INSPECTION

Date of Assignment:	08/07/2024	
Date Inspected:	08/07/2024	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	10.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,736.00 FS	*2,188.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	209.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - LH	Cracked	49.00 FS	*38.56 FS
4	1		*FRONT BUMPER GRILLE CENTER	Missing	201.00 FS	*160.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Serviceable	645.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT - LH	Cracked	357.00 FS	*285.60 FS
7	1		*FRONT BUMPER COVER TRIM - LH	Missing	204.00 FS	*163.20 FS
8	1		*FRONT ADAPTER WHEEL HOUSING LINER - LH	Serviceable	48.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,784.00 FS	*1,427.20 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Cracked	235.00 FS	*187.60 FS
11	1		*STICKER FOR AIR CONDITIONER	Necessary	10.00 FS	*7.52 FS
12	1		*SIGN CAUTION STICKER	Necessary	25.00 FS	*19.44 FS
13	1		*FRONT AIR GUIDE GRILLE - LH	Missing	235.00 FS	*188.00 FS
14	1		*FRONT BUMPER COVER	Cracked	153.00 FS	*122.40 FS
15	1		*FRONT FOAM FILLER PIECE	Cracked	237.00 FS	*189.60 FS
16	1		*FRONT REINFORCEMENT BEAM	Bent	1,055.00 FS	*844.00 FS
17	1		*FRONT BRACKET	Serviceable	30.00 FS	*- FS
18	1		*LED HEADLIGHT - LH	Broken	6,647.00 FS	*5,317.60 FS
19	1		*LED HEADLIGHT POWER MODULE - LH	Serviceable	904.00 FS	*- FS
20	1		*LED HEADLIGHT CONTROL UNIT	Serviceable	664.00 FS	*- FS
21	1		*LED HEADLIGHT LIFT CYLINDER - LH	Cracked	170.00 FS	*136.00 FS
22	1		*LED HEADLIGHT HOSE - LH	Cut	86.00 FS	*68.56 FS
23	1		*WASH WATER RESERVOIR	Deformed	238.00 FS	*190.00 FS
24	1		*FRONT WINDSCREEN WASHER PUMP	Serviceable	147.00 FS	*- FS
25	1		*SEAL	Not Necessary	4.00 FS	*- FS
26	1		*STRAINER	Not Necessary	26.00 FS	*- FS
27	1		*END CAP	Not Necessary	26.00 FS	*- FS
28	1		*BONNET	Bent	3,392.00 FS	*2,713.60 FS
29	1		*BONNET ATTACHMENT PARTS	Not Necessary	184.00 FS	*- FS
30	2		*BONNET LID HINGE - LH / RH	Bent	150.00 FS	*119.04 FS
31	2		*BONNET STOP BUFFER	Not Necessary	16.00 FS	*- FS
32	1		*BONNET LOCK LATCH	Not Necessary	116.00 FS	*- FS
33	2		*BONNET STRICKER - LH / RH	Not Necessary	274.00 FS	*- FS
34	1		*BONNET EDGE PROTECTION	Necessary	35.00 FS	*27.84 FS
35	1		*BONNET HOOK	Not Necessary	79.00 FS	*- FS
36	2		*BONNET LID LOCK MICRO SWITCH	Not Necessary	491.00 FS	*- FS
37	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	71.00 FS	*- FS
38	1		*BONNET LID LOCK COVER	Not Necessary	12.00 FS	*- FS
39	1		*BONNET SOUND ABSORBER	Not Necessary	275.00 FS	*- FS
40	1		*PLENUM CHAMBER COVER	Scratched	296.00 FS	*236.80 FS
41	1		*FRONT WHEEL HOUSING LINER - LH	Cracked	204.00 FS	*162.80 FS
42	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - LH	Not Necessary	105.00 FS	*- FS
43	1		*RADIATOR AIR GUIDE - LH	Cracked	59.00 FS	*46.88 FS
44	1		*RADIATOR AIR GUIDE - RH	Serviceable	86.00 FS	*- FS
45	1		*RADIATOR SEAL - RH OUTER	Serviceable	10.00 FS	*- FS
46	1		*RADIATOR AIR GUIDE - UPPER CENTER	Serviceable	21.00 FS	*- FS
47	1		*FRONT LOCK CARRIER	Cracked	908.00 FS	*726.00 FS
48	6		*RADIATOR COOLANT 1.0 LTR	Necessary	332.00 FS	*265.44 FS
49	1		*A/C CONDENSER	Not Necessary	846.00 FS	*- FS
50	1		*ADDITIONAL RADIATOR	Not Necessary	987.00 FS	*- FS
51	1		*RADIATOR	Not Necessary	1,177.00 FS	*- FS
52	2		*BRACKET	Not Necessary	94.00 FS	*- FS
53	1		*SEAL RING	Not Necessary	16.00 FS	*- FS
54	1		*SEAL RING	Not Necessary	15.00 FS	*- FS
55	2		*FRONT PARKING AID - INNER/OUTER	Not Necessary	572.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	4		*FRONT PARKING AID SEAL RING	Not Necessary	11.00 FS	*- FS
57	1		*FRONT NO. PLATE	Necessary	60.00 FS	*60.00 FS
58	1		*SUNDRIES	Necessary	1,000.00 FS	*65.68 FS
59	1		*INTAKE AIR GUIDE LOWER (Supplementary)	Cracked	61.00 FS	*48.72 FS
60	1		*SET FRONT BUMPER SENSOR WIRING (Supplementary)	Cut	804.00 FS	*642.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	29,884.00	16,650.48
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	400.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM AND REGAS AND PRESSURISE COOLING SYSTEM	New	1,600.00	1,600.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO REPAIR BOTH FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	3,000.00
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDER	New	3,700.00	2,200.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			12,072.00	7,972.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >