

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLL 272B

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BUMPER SET FR (N)	TO REPAIR SEE LABOUR	\$836.40	\$0.00
1	CLIP FRT BUMPER (N)	NOT NECESSARY	\$1.50	\$0.00
	LESS 20.00%		(\$167.58)	\$0.00
			\$670.32	\$0.00
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRT LICENCE PLATE (SN)	SCRATCHED	\$60.00	\$60.00
			\$60.00	\$60.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOR CHARGES TO REPAIR RAD SUPPORT RENEW FRONT BUMPER. INCLUSIVE OF THE REPAIR OF BUMPER SET FR		\$860.00	\$215.00
	CHARGES TO SPRAY PAINTING SAME		\$660.00	\$350.00
	REMOVE AND INSTALL BOTH HEADLAMP AND CHECK FRT LIGHT SYSTEM	NOT NECESSARY	\$48.00	\$0.00
	PRESSURE TEST AND LEAK TEST	NOT NECESSARY	\$55.00	\$0.00
			\$1,623.00	\$565.00
GRAND TOTAL			\$2,353.32	\$625.00
RECOMMENDED COST OF REPAIRS				\$625.00
D 4 D . ()				

MARKET VALUE: \$42,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$20,788.00=NETT VALUE: \$21,212.00

Report Ref No: CS/FCI24070134/Unp3

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.