

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24070138/RQP3E2**Date:** 23/08/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SMK8665S **Insured Vehicle No :** SND531Y

Date of Loss: 05/07/2024 Nature of Claim: TP Claim No: DMPC2400847H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK8665S**

Make & Model: SKODA KODIAQ, 1.4 TSI AMBITION PLUS (A) Engine No: CZD734467

Reg. Date: 26/04/2019 (Man. Year: 2018) Chassis No: TMBKC7NS7K8036341

Colour: Grey Odometer: 231863 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,905.33	3,072.39	832.94	21.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,520.00	4,040.00	2,480.00	38.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	10,425.33	7,112.39	3,312.94	31.78
+ GST 9.00/9.00% (\$\$)	938.28	640.12	298.16	31.78
Nett Amount (\$\$)	11,363.61	7,752.51	3,611.10	31.78

INSPECTION

Date of Assignment: 08/07/2024

Date Inspected: 10/07/2024 Inspected At: Volkswagen Group Singapore Pte Ltd (HQ)
247 ALEXANDRA ROAD
Singapore 159934

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2024)
Parts:	144	SKODA KODIAQ 1.4 TSI AMBITION PLUS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMK8665S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR REAR BUMPER (TOP)	Deformed	2,208.70 FS	*2,208.70 FS
2	1		*COVER FOR REAR BUMPER (BOTTOM)	Scratched	473.78 FS	*473.78 FS
3	1		*COVER FOR TOWING	Not Necessary	30.84 FS	*- FS
4	1		*GUIDE PIEC LHR BUMPER BRACKET (SIDE)	Not Necessary	58.00 FS	*- FS
5	1		*GUIDE PIEC RHR BUMPER BRACKET (SIDE)	Not Necessary	58.00 FS	*- FS
6	1		*GUIDE PIEC LHR BUMPER BRACKET (OUTER)	Not Necessary	59.88 FS	*- FS
7	1		*GUIDE PIEC RHR BUMPER BRACKET (OUTER)	Not Necessary	59.88 FS	*- FS
8	1		*RETAINING REAR BUMPER BRACKET (CTR)	Not Necessary	92.64 FS	*- FS
9	1		*BUMP STRIP	Not Necessary	267.66 FS	*- FS
10	1		*SENSOR BRACKET	Necessary	17.81 FS	*17.81 FS
11	1		*SENSOR BRACKET	Necessary	17.81 FS	*17.81 FS
12	6		*SEAL RING SATIN BLACK	Necessary	39.48 FS	*39.48 FS
13	1		*SENSOR PRIMED	Not Necessary	206.04 FS	*- FS
14	1		*SKODA EMBLEM	Necessary	80.55 FS	*80.55 FS
15	1		*2K PLASTIC ADHESIVE	Necessary	94.98 FS	*94.98 FS
16	1		*BONDING AGENT FOR PLASTIC	Necessary	78.24 FS	*78.24 FS
17	1		*SENSOR BRACKET	Necessary	15.26 FS	*15.26 FS
18	1		*SENSOR BRACKET	Necessary	15.26 FS	*15.26 FS
19	1		*SENSOR BRACKET	Necessary	15.26 FS	*15.26 FS
20	1		*SENSOR BRACKET	Necessary	15.26 FS	*15.26 FS
Total Parts (S\$)					3,905.33	3,072.39

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	3,360.00	1,680.00
4	SPRAY PAINTING	New	2,400.00	1,600.00
Gross Labour Cost (S\$)			6,520.00	4,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >