

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO YQ 6134Y

REPLACEMENT OF PARTS						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	REAR TAILLAMP - LH	CRACKED	\$298.20	\$298.20		
1	REAR TAILLAMP BRACKET - LH	TO REPAIR SEE LABOUR	\$98.20	\$0.00		
1	REAR NUMBER PLATE BRACKET	NOT NECESSARY	\$90.60	\$0.00		
	LESS 25.00% DISCOUNT		(\$121.75)	(\$74.55)		
			\$365.25	\$223.65		

Special Nett						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	REAR NUMBER PLATE	NOT NECESSARY	\$50.00	\$0.00		
1	REAR BUMPER	DENTED	\$1,200.00	\$800.00		
1	REAR BUMPER BRACKET N/S	BENT	\$90.00	\$90.00		
1	SET REAR BUMPER STICKER	NECESSARY	\$30.00	\$30.00		
1	SET REAR REVERSE SENSOR	SERVICEABLE	\$300.00	\$0.00		
1	REAR REFLECTOR N/S	CRACKED	\$35.00	\$35.00		
			\$1,705.00	\$955.00		

Labour					
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR TAILLAMP BRACKET - LH.		\$800.00	\$450.00	
	TO REMOVE & REFIX REAR BUMPER SENSOR.		\$80.00	\$30.00	
	TO SPRAY PAINTING.		\$520.00	\$300.00	
			\$1,400.00	\$780.00	

GRAND TOTAL	\$3,470.25	\$1,958.65		
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$1,500.00		
Report Ref No: CS/AGI24060046/Unp3m4				

CKS

MARCUS CHUA KANG SENG Licensed Appraiser