

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24070150/EPA3Q2**Date:** 08/12/2025REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SHD5688S**Insured Vehicle No :** SHD2663H

Date of Loss: 08/04/2024

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD5688S**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

Engine No: 2ZR2C00855

Reg. Date: 17/01/2019 (Man. Year: 2018)

Chassis No: JTDKB3FU503079341

Colour: Red

Odometer: 710398 km

Engine Capacity: 1798 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Wanli 5 mm

Rear Left Side: Wanli 5 mm

Front Right Side: Wanli 5 mm

Rear Right Side: Wanli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,530.36	1,469.93	7,060.43	82.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,550.00	950.00	3,600.00	79.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,080.36	2,419.93	10,660.43	81.50
Approved Total (Overridden) (S\$)		1,900.00		
Nett Amount (S\$)	13,080.36	1,900.00	11,180.36	85.47

INSPECTION

Date of Assignment: 09/07/2024

Date Inspected: 09/07/2024

Inspected At:

Trans-cab Auto Services Pte Ltd

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

We have checked and confirmed that all part prices are correct. The actual work carried out and listed as labour and spray painting is accurate, and the fees charged for labour and spray painting are correct.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Dec 2025)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD5688S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY FRONT DOOR LH	Dented	1,641.36 FL	*1,641.36 FL
2	1		*FRAME SUB-ASSY ,FRONT DOOR OUTSIDE HANDLE LH	Not Necessary	243.81 FL	*- FL
3	1		*HANDLE ASSY FRONT DOOR OUTSIDE LH	Not Necessary	493.40 FL	*- FL
4	1		*WEATHERSTRIP FRONT DOOR LH	Not Necessary	292.32 FL	*- FL
5	1		*HINGE ASSY ,FRONT DOOR LOWER LH	Not Necessary	139.86 FL	*- FL
6	1		*HINGE ASSY ,FRONT DOOR UPPER LH	Not Necessary	123.06 FL	*- FL
7	1		*TAPE BLACK OUT NO .1 FRT LH	Necessary	16.91 FL	*16.91 FL
8	1		*TAPE BLACK OUT NO .2 FRT LH	Necessary	55.02 FL	*55.02 FL
9	1		*TAPE BLACK OUT NO .3 FRT LH	Necessary	33.29 FL	*33.29 FL
10	1		*MOTOR ASSY POWER WINDOW REGULATOR FRT LH	Not Necessary	1,161.83 FL	*- FL
11	1		*REGULATOR SUB-ASSY FRONT DOOR WINDOW LH	Not Necessary	300.62 FL	*- FL
12	1		*PANEL SUB-ASSY REAR DOOR LH	Repair	1,634.33 FL	*- FL
13	1		*PANEL SUB-ASSY REAR DOOR OUTSIDE HANDLE LH	Not Necessary	243.81 FL	*- FL
14	1		*HANDLE ASSY REAR DOOR OUTSIDE LH	Not Necessary	123.06 FL	*- FL
15	1		*WEATHERSTRIP REAR DOOR OPENING TRIM LH	Not Necessary	369.60 FL	*- FL
16	1		*HINGE ASSY REAR DOOR LOWER LH	Not Necessary	109.62 FL	*- FL
17	1		*HINGE ASSY REAR DOOR UPPER LH	Not Necessary	124.74 FL	*- FL
18	1		*TAPE BLACK OUT NO.1REAR LH	Not Necessary	27.62 FL	*- FL
19	1		*TAPE BLACK OUT NO.2 REAR LH	Not Necessary	44.00 FL	*- FL
20	1		*TAPE BLACK OUT NO.3 REAR LH	Not Necessary	19.43 FL	*- FL
21	1		*COVER REAR BUMPER	Not Necessary	612.68 FL	*- FL
22	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	167.48 FL	*- FL
23	1		*SEAL REAR BUMPER SIDE LH	Not Necessary	149.21 FL	*- FL
24	1		*PANEL SUB-ASSY QUARTER LH	Not Necessary	1,099.46 FL	*- FL
25	1		*LINER REAR WHEEL HOUSE LH	Not Necessary	176.09 FL	*- FL
26	1		*MOULDING ASSY BODY ROCKER PANEL LH	Repair	624.54 FL	*- FL
27	2		*SET DOOR TRIM CLIP	Not Necessary	70.00 FS	*- FS
28	2		*SET DOOR WEATHERSTRIP CLIP	Not Necessary	130.00 FS	*- FS
29	1		*DOOR STICKER TRANSCAB	Necessary	100.00 FS	*80.00 FS
30	1		*DOOR STICKER TEL NO	Necessary	100.00 FS	*80.00 FS
31	1		*TYRE	Not Necessary	350.00 FS	*- FS
32	1		*SET CLIP ROCKER PANEL MOULDING	Not Necessary	65.00 FS	*- FS
33	1		*SET FENDER CLIP	Not Necessary	130.00 FS	*- FS
34	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,037.15	1,906.58
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,506.79	436.65
Total Parts (\$\$)	8,530.36	1,469.93

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	20.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	50.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	250.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	600.00
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	30.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
8	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			4,550.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >