

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070151/RMA3Q2
Date: 19/11/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002571_01
Claimant Vehicle No : SDW4455B Insured Vehicle No : SLE3461P
Date of Loss: 06/07/2024 Nature of Claim: TP Claim No: MFL2024D0008734

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDW4455B
Make & Model: MERCEDES-BENZ GLB 180, 1.3 PROGRESSIVE LINE (A) Engine No: 28281480076626
Reg. Date: 19/03/2024 (Man. Year: 2023) Chassis No: W1N2476842W350365
Colour: Grey Odometer: 6163 km
Engine Capacity: 1332 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,614.80	6,659.98	4,954.82	42.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	1,880.00	640.00	25.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,134.80	8,539.98	5,594.82	39.58
+ GST 9.00/9.00% (S\$)	1,272.13	768.60	503.53	39.58
Nett Amount (S\$)	15,406.93	9,308.58	6,098.35	39.58
+ Car Rental (2.0 x S\$100.00/day + 9.00% GST) (S\$)		218.00		
Nett Liability (S\$)		9,526.58		

INSPECTION

Date of Assignment: 12/08/2024
Date Inspected: 12/08/2024 Inspected At: Cycle & Carriage Industries Pte Ltd (Pandan Loop)
188 Pandan Loop
Singapore 128378
Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2024)
Parts:	M1-SUV	MERCEDES-BENZ GLB 180 1.3 PROGRESSIVE LINE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDW4455B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	15.00 FS	*15.00 FS
2	1		*REAR BUMPER	Deformed	1,520.45 FS	*1,520.45 FS
3	1		*CTR BASIC CARRIER FOR BUMPER	Not Necessary	139.63 FS	*- FS
4	1		*STEP PLATE	Scratched	251.31 FS	*251.31 FS
5	1		*REAR LOWER BUMPER	Deformed	604.52 FS	*604.52 FS
6	1		*CHROME COVER ,REAR BUMPER	Cracked	1,474.90 FS	*1,474.90 FS
7	1		*BOTTOM LEFT TRIM STRIP	Cut	141.96 FS	*141.96 FS
8	1		*LEFT EXHAUST COVER	Cut	180.35 FS	*180.35 FS
9	1		*LOWER LHR BRACKET BUMPER	Not Necessary	32.86 FS	*- FS
10	1		*LHR OUTER RADAR ABSORBER	Not Necessary	51.02 FS	*- FS
11	1		*LHR RADAR CONTROL UNIT COMPLETE	Shorted	1,854.91 FS	*1,854.91 FS
12	1		*LHR RADAR BRACKET	Necessary	34.43 FS	*34.43 FS
13	1		*LHR BASIC CARRIER FOR BUMPER	Not Necessary	55.10 FS	*- FS
14	1		*LEFT BUMPER LATERAL SUPPORT	Not Necessary	115.63 FS	*- FS
15	1		*LHR REFLECTOR LENS	Not Necessary	33.05 FS	*- FS
16	1		*COVER SUBSTRUCTURE	Not Necessary	177.61 FS	*- FS
17	1		*DISTANCE SENSOR	Shorted	329.75 FS	*329.75 FS
18	1		*DECOUPLING RING	Necessary	7.63 FS	*7.63 FS
19	1		*LEFT REAR LAMP COMBINATION	Not Necessary	712.23 FS	*- FS
20	1		*REAR END PANEL	Not Necessary	2,918.32 FS	*- FS
21	1		*REAR CROSS MEMBER	Not Necessary	719.37 FS	*- FS
22	1		*REFLECTING EMITTER	Cut	49.88 FS	*49.88 FS
23	1		*ELECTRICAL WIRING HARNESS	Cut	194.89 FS	*194.89 FS
Total Parts (\$\$)					11,614.80	6,659.98

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
2	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,200.00	960.00
3	RESPRAY ON REAR BUMPER AND ACCIDENT AFFECTED AREA	New	1,200.00	800.00
Gross Labour Cost (\$\$)			2,520.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >