

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24070152/AMA3Q2**Date:** 19/12/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7230130330  
**Claimant Vehicle No :** GBB9363J **Insured Vehicle No :** GBG7718G  
 Date of Loss: 08/07/2024 Nature of Claim: TP Claim No: 1985963905SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB9363J**  
 Make & Model: NISSAN NV200, 1.5 D MT ABS AIRBAG 2WD 6DR (A) Engine No: K9KF276D089714  
 Reg. Date: 31/08/2010 (Man. Year: 2010) Chassis No: JN1YBAM20U0002999  
 Colour: Grey Odometer: 239668 km  
 Engine Capacity: 1461 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14  
 Front Left Side: Grenlander 6 mm Rear Left Side: Grenlander 6 mm  
 Front Right Side: Grenlander 6 mm Rear Right Side: Grenlander 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                                       | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                                       | 25,896.64         | 9,145.17          | 16,751.47         | 64.69         |
| Miscellaneous Items                                         | 0.00              | 0.00              | 0.00              |               |
| Labour                                                      | 7,290.00          | 2,870.00          | 4,420.00          | 60.63         |
| Paintwork Labour                                            | 0.00              | 0.00              | 0.00              |               |
| Towing                                                      | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>                         | <b>33,186.64</b>  | <b>12,015.17</b>  | <b>21,171.47</b>  | <b>63.80</b>  |
| <b>Approved Total (Overridden) (S\$)</b>                    |                   | <b>9,000.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                                    | <b>33,186.64</b>  | <b>9,000.00</b>   | <b>24,186.64</b>  | <b>72.88</b>  |
| <b>+ Car Rental (11.0 x S\$80.00/day + 9.00% GST) (S\$)</b> |                   | 959.20            |                   |               |
| <b>Nett Liability (S\$)</b>                                 |                   | <b>9,959.20</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>                          |                   | <b>9,950.00</b>   |                   |               |

INSPECTION

Date of Assignment: 09/07/2024  
 Date Inspected: 09/07/2024 Inspected At: Ms Car Auto Pte Ltd (HQ)  
 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT  
 Singapore 415875  
 Estimated Period of Repair: 10.0 days

**Adjuster:** ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                    | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR NUMBER PLATE LAMP        | Not Necessary | 120.40 FL   | *- FL        |
| 2   | 1   |          | *REAR BUMPER                   | Distorted     | 632.70 FL   | *632.70 FL   |
| 3   | 2   |          | *REAR BUMPER SIDE HOLDER       | Not Necessary | 86.60 FL    | *- FL        |
| 4   | 1   |          | *REAR BUMPER SPONGE            | Cracked       | 128.90 FL   | *128.90 FL   |
| 5   | 2   |          | *REAR BUMPER REFLECTOR         | Not Necessary | 85.00 FL    | *- FL        |
| 6   | 1   |          | *REAR END PANEL OUTER          | Distorted     | 485.20 FL   | *485.20 FL   |
| 7   | 1   |          | *REAR END PANEL INNER          | Distorted     | 697.40 FL   | *697.40 FL   |
| 8   | 1   |          | *REAR END PANEL TOP GARNISH    | Deformed      | 128.40 FL   | *128.40 FL   |
| 9   | 2   |          | *TAILLAMP                      | Cracked       | 517.40 FL   | *517.40 FL   |
| 10  | 1   |          | *TAILLAMP PANEL RH             | Repair        | 459.50 FL   | *- FL        |
| 11  | 1   |          | *TAILGATE LH                   | Distorted     | 1,545.00 FL | *1,545.00 FL |
| 12  | 1   |          | *TAILGATE LOCK UPPER LH        | Not Necessary | 215.50 FL   | *- FL        |
| 13  | 1   |          | *TAILGATE LOCK LOWER LH        | Jammed        | 159.30 FL   | *159.30 FL   |
| 14  | 1   |          | *TAILGATE LOCK ACTUATOR LH     | Jammed        | 379.10 FL   | *379.10 FL   |
| 15  | 1   |          | *TAILGATE WEATHERSTRIP LH      | Not Necessary | 95.90 FL    | *- FL        |
| 16  | 2   |          | *TAILGATE HINGE LH             | Not Necessary | 205.80 FL   | *- FL        |
| 17  | 1   |          | *TAILGATE INNER TRIM BOARD LH  | Not Necessary | 145.20 FL   | *- FL        |
| 18  | 1   |          | *TAILGATE OUTER GARNISH LH     | Deformed      | 351.50 FL   | *351.50 FL   |
| 19  | 1   |          | *TAILGATE WIPER MOTOR LH       | Damaged       | 355.20 FL   | *355.20 FL   |
| 20  | 1   |          | *NISSAN LOGO                   | Necessary     | 58.90 FL    | *58.90 FL    |
| 21  | 1   |          | *NV200 EMBLEM                  | Necessary     | 69.50 FL    | *69.50 FL    |
| 22  | 1   |          | *TAILGATE RH                   | Distorted     | 1,102.50 FL | *1,102.50 FL |
| 23  | 1   |          | *TAILGATE LOCK UPPER RH        | Not Necessary | 215.50 FL   | *- FL        |
| 24  | 1   |          | *TAILGATE LOCK LOWER RH        | Jammed        | 159.30 FL   | *159.30 FL   |
| 25  | 1   |          | *TAILGATE WEATHERSTRIPE RH     | Not Necessary | 83.60 FL    | *- FL        |
| 26  | 1   |          | *TAILGATE INNER TRIM BOARD RH  | Not Necessary | 145.20 FL   | *- FL        |
| 27  | 2   |          | *TAILGATE HINGE RH             | Not Necessary | 205.80 FL   | *- FL        |
| 28  | 1   |          | *TAILGATE FRAME WEATHERSTRIPE  | Cut           | 215.00 FL   | *215.00 FL   |
| 29  | 1   |          | *FLOOR PANEL                   | Repair        | 2,162.30 FL | *- FL        |
| 30  | 1   |          | *FLOOR PANEL CARPET            | Not Necessary | 652.10 FL   | *- FL        |
| 31  | 1   |          | *REAR RH BODY PANEL            | Not Necessary | 1,636.90 FL | *- FL        |
| 32  | 1   |          | *REAR RH BODY PANEL INNER      | Not Necessary | 1,201.30 FL | *- FL        |
| 33  | 1   |          | *REAR RH BODY PANEL AIR GRILLE | Not Necessary | 45.30 FL    | *- FL        |
| 34  | 1   |          | *REAR EXHAUST PIPE             | Not Necessary | 689.40 FL   | *- FL        |
| 35  | 1   |          | *REAR EXHAUST PIPE MOUNTING    | Not Necessary | 35.10 FL    | *- FL        |
| 36  | 1   |          | *FRONT BUMPER                  | Deformed      | 674.50 FL   | *674.50 FL   |
| 37  | 2   |          | *FRONT BUMPER SIDE HOLDER      | Not Necessary | 70.40 FL    | *- FL        |
| 38  | 1   |          | *FRONT BUMPER SPONGE           | Cracked       | 121.30 FL   | *121.30 FL   |
| 39  | 1   |          | *FRONT BUMPER REINFORCEMENT    | Not Necessary | 591.90 FL   | *- FL        |
| 40  | 2   |          | *FRONT BUMPER SIDE COVER       | Not Necessary | 196.80 FL   | *- FL        |
| 41  | 1   |          | *FRONT BUMPER UNDERCOVER       | Not Necessary | 298.00 FL   | *- FL        |
| 42  | 1   |          | *FRONT GRILLE                  | Cracked       | 344.10 FL   | *344.10 FL   |
| 43  | 1   |          | *FRONT GRILLE LOGO             | Necessary     | 59.70 FL    | *59.70 FL    |
| 44  | 1   |          | *FRONT GRILLE MOULDING         | Not Necessary | 122.40 FL   | *- FL        |
| 45  | 2   |          | *FRONT APRON PANEL             | Torn          | 697.20 FL   | *697.20 FL   |
| 46  | 1   |          | *HEADLAMP                      | N/S Cracked   | 1,158.40 FL | *579.20 FL   |
| 47  | 1   |          | *BONNET                        | Not Necessary | 882.90 FL   | *- FL        |
| 48  | 1   |          | *BONNET LOCK                   | Not Necessary | 59.10 FL    | *- FL        |
| 49  | 2   |          | *BONNET HINGE                  | Not Necessary | 164.80 FL   | *- FL        |
| 50  | 1   |          | *FRONT SUPPORT PANEL           | Repair        | 535.20 FL   | *- FL        |
| 51  | 1   |          | *AIR CON CONDENSER             | Not Necessary | 688.20 FL   | *- FL        |
| 52  | 2   |          | *AIR CON CONDENSER UPPER GUIDE | Not Necessary | 136.80 FL   | *- FL        |
| 53  | 2   |          | *AIR CON CONDENSER LOWER GUIDE | Not Necessary | 150.40 FL   | *- FL        |
| 54  | 1   |          | *RADIATOR                      | Not Necessary | 765.70 FL   | *- FL        |
| 55  | 1   |          | *RADIATOR FAN COWLING          | Not Necessary | 180.70 FL   | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount     |
|-----|-----|----------|---------------------------------------|---------------|-------------|------------|
| 56  | 1   |          | *RADIATOR FAN BLADE                   | Not Necessary | 118.70 FL   | *- FL      |
| 57  | 1   |          | *RADIATOR FAN MOTOR                   | Not Necessary | 424.70 FL   | *- FL      |
| 58  | 1   |          | *INTERCOOLER                          | Not Necessary | 1,855.60 FL | *- FL      |
| 59  | 2   |          | *FRONT FENDER                         | Not Necessary | 1,110.40 FL | *- FL      |
| 60  | 1   |          | *REAR NUMBER PLATE                    | Bent          | 30.00 FS    | *30.00 FS  |
| 61  | 1   |          | *REAR NUMBER PLATE HOLDER             | Deformed      | 30.00 FS    | *30.00 FS  |
| 62  | 1   |          | *SET REAR BUMPER CLIPS                | Necessary     | 50.00 FS    | *30.00 FS  |
| 63  | 1   |          | *SET REVERSE SENSOR                   | Damaged       | 280.00 FS   | *200.00 FS |
| 64  | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS | Necessary     | 20.00 FS    | *20.00 FS  |
| 65  | 1   |          | *SET REAR END PANEL SEALANT           | Necessary     | 100.00 FS   | *60.00 FS  |
| 66  | 2   |          | *SET TAILGATE INNER TRIM BOARD CLIPS  | Not Necessary | 60.00 FS    | *- FS      |
| 67  | 1   |          | *SET TAILGATE OUTER GARNISH CLIPS LH  | Necessary     | 30.00 FS    | *30.00 FS  |
| 68  | 1   |          | *SET TAILGATE GLASS SEALANT LH        | Necessary     | 60.00 FS    | *40.00 FS  |
| 69  | 1   |          | *70KM/H STICKER                       | Not Necessary | 15.00 FS    | *- FS      |
| 70  | 1   |          | *SET TAILGATE GLASS SEALANT RH        | Necessary     | 60.00 FS    | *40.00 FS  |
| 71  | 1   |          | *REAR CAMERA                          | Not Necessary | 480.00 FS   | *- FS      |
| 72  | 1   |          | *SET FLOOR PANEL CARPET CLIPS         | Not Necessary | 100.00 FS   | *- FS      |
| 73  | 1   |          | *FLOOR PANEL SEALANT                  | Not Necessary | 100.00 FS   | *- FS      |
| 74  | 1   |          | *SET REAR RH BODY PANEL SEALANT       | Not Necessary | 60.00 FS    | *- FS      |
| 75  | 1   |          | *FRONT NUMBER PLATE                   | Dented        | 30.00 FS    | *30.00 FS  |
| 76  | 1   |          | *FRONT NUMBER PLATE HOLDER            | Deformed      | 30.00 FS    | *30.00 FS  |
| 77  | 1   |          | *SET FRONT BUMPER CLIPS               | Necessary     | 30.00 FS    | *30.00 FS  |
| 78  | 1   |          | *SET FRONT BUMPER UNDERCOVER CLIPS    | Not Necessary | 30.00 FS    | *- FS      |
| 79  | 1   |          | *SET FRONT GRILLE CLIPS               | Necessary     | 20.00 FS    | *20.00 FS  |
| 80  | 2   |          | *SET FRONT APRON CLIPS                | Necessary     | 40.00 FS    | *40.00 FS  |
| 81  | 1   |          | *RADIATOR COOLANT                     | Not Necessary | 50.00 FS    | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                  |                  |
|----------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$)</b>                                    | <b>28,584.60</b> | <b>10,091.30</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$)</b> | 2,687.96         | 946.13           |
| <b>Total Parts (\$)</b>                                  | <b>25,896.64</b> | <b>9,145.17</b>  |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                 | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                             |          |                 |                 |
| 1                               | PANEL BEATING                               | New      | 3,000.00        | 1,400.00        |
| 2                               | SPRAY PAINTING                              | New      | 2,500.00        | 1,000.00        |
| 3                               | WIRING                                      | New      | 100.00          | 60.00           |
| 4                               | TO SPRAY TUFF COAT                          | New      | 250.00          | 100.00          |
| 5                               | TO REMOVE REVERSE SENSOR                    | New      | 100.00          | 50.00           |
| 6                               | TO REMOVE REAR CAMERA                       | New      | 100.00          | 0.00            |
| 7                               | TO REMOVE UPHOLSTERY AND FLOOR PANEL CARPET | New      | 250.00          | 80.00           |
| 8                               | TO TRANSFER TAILGATE LH AND RH FITTINGS     | New      | 300.00          | 60.00           |
| 9                               | TO REMOVE TAILGATE LH AND RH GLASSES        | New      | 240.00          | 60.00           |
| 10                              | TO REMOVE EXHAUST PIPE                      | New      | 150.00          | 0.00            |
| 11                              | TO REMOVE CONDENSER & TO TOP UP AIR CON GAS | New      | 120.00          | 0.00            |
| 12                              | TO REMOVE RADIATOR & TO TOP UP COOLANT      | New      | 120.00          | 0.00            |
| 13                              | TOWING CHARGES                              | New      | 60.00           | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                             |          | <b>7,290.00</b> | <b>2,870.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >