

ASS. REC. BY:

Tajm

REF:

CD/LPC24070155/Tp43

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$126k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNH5134G

Yr Regn:

2022, 11

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3 Hybrid

c.c

1496

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

126948

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMB3 P2SAA N1151155

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: ☒ NII / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45 R18

R:

~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Piven 37

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

9/7/24

Survey held at

Car Times

Des. of Damages: Frt / Rear / O/S / N/S / U/G / Rooftop or

Rear N/S

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Rep. Format:

Lump Sum / L.B.E. (\$



AUTOLUTION

CarTimes Autolution Pte Ltd

#02-04 Singapore 575722

Tel : 6471 5111

Email : claims@cartimes.com.sg

VEHICLE NO: SNH5134G

CHASSIS NO: JM6BP2SAAN1151155

DESCRIPTION	REPAIRER'S ESTIMATE(S\$)
<u>PARTS (LIST ITEMS)</u>	
REAR BUMPER	\$ 1,200.00
REAR BUMPER RETAINER LHS	\$ 150.00
REAR BUMPER REFLECTOR LHS	\$ 150.00
TAIL LAMP LHS	\$ 1,500.00
REAR FENDER LHS	\$ 1,560.00
REAR FENDER INNER SHIELD LHS	\$ 300.00
REAR BLIND SPOT ASSIST MODULE	\$ 1,900.00
REAR BLIND SPOT ASSIST MODULE BRACKET	\$ 150.00
	20% \$ 6,910.00
	\$ 1,382.00
	\$ 5,528.00
<u>SPECIAL NETT ITEMS</u>	
REAR BUMPER CLIPS 1 SET	\$ 50.00
Total	\$ 50.00
TOTAL PARTS	\$ 5,578.00

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,600.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00	500
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	30
4	To provide anti-rust treatment on affected areas	\$ 100.00	30
5	Dignostic Check	\$ 100.00	✓
6	Remove & refit petrol tank	\$ 150.00	60
7	Blind spot assist programming	\$ 200.00	X
Labour Total :		\$ 3,850.00	
TOTAL (PARTS & LABOUR):		\$ 9,428.00	

Tanfikh 97495749/62563561
 9/7/24 @ 5pm
 L/S Repair after repair
 Tanfikh @ 1khankh
 5 days