



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLJ 83R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR LH DOOR PANEL	BENT	\$1,869.16	\$1,869.16
1	REAR LH DOOR SEAL	NECESSARY	\$107.47	\$107.47
1	REAR LH FENDER OUTER GARNISH	DENTED/CUT	\$65.42	\$65.42
1	REAR LH WHEEL RIM	DENTED	\$1,130.84	\$1,130.84
1	REAR LH KNUCKLE ARM	BENT	\$672.89	\$672.89
1	REAR LH KNUCKLE HUB + BEARING	NECESSARY	\$149.53	\$149.53
1	REAR LH UPPER AFTER LINK	SERVICEABLE	\$18.69	\$0.00
1	REAR LH LOWER AFTER LINK	SERVICEABLE	\$224.29	\$0.00
1	REAR LH UPPER FORE LINK	SERVICEABLE	\$18.69	\$0.00
1	REAR LH TOE LINK	SERVICEABLE	\$17.75	\$0.00
1	REAR LH LOWER FORE LINK	SERVICEABLE	\$224.29	\$0.00
1	SIDE SKIRT RH	SERVICEABLE	\$364.48	\$0.00
1	REAR RH WHEEL RIM	DENTED	\$1,130.84	\$1,130.84
1	FRONT RH WHEEL RIM	DENTED	\$1,130.84	\$1,130.84
1	REAR LH FENDER PANEL (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
1	FRONT BUMPER (NPA)	TO REPAIR SEE LABOUR	\$0.00	\$0.00
	<b>LESS 10.00% DISCOUNT</b>		(\$712.52)	(\$625.70)
			<b>\$6,412.66</b>	<b>\$5,631.29</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	REAR FENDER GARNISH CLIPS (SN)	NECESSARY	\$50.00	\$50.00
1	SIDE SKIRT CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
			<b>\$150.00</b>	<b>\$50.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF REAR LH FENDER PANEL AND FRONT BUMPER		\$800.00	\$300.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR LH DOOR, REAR LH FENDER, FRONT BUMPER, FRONT & REAR RH WHEEL RIM, ETC		\$1,300.00	\$440.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS		\$150.00	\$60.00
	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT		\$120.00	\$80.00
	TO REMOVE AND REFIT REAR UNDERCARRIAGE PARTS TO ENABLE REPAIR		\$300.00	\$80.00
	TO TUFF KOTE & UNDERSEAL MATERIALS		\$100.00	\$30.00
	TO CHECK WIRING & ELECTRICAL SYSTEM		\$80.00	\$20.00
	RE-COATING AND POLISHING FOR ACCIDENT PORTION (ADDITIONAL)		\$430.00	\$380.00
			\$3,280.00	\$1,390.00
GRAND TOTAL			\$9,842.66	\$7,071.29
	RECOMMENDED COST OF REPAIRS			\$7,071.29
Report Ref No: CS/FCI24060047/Knp3m4				

## KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.