



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24060047/Knp3m4
16 RAFFLES QUAY	Date:	07/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1483Y	Veh. Inspected	SLJ 83R
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24004838MFCT	Excess	\$0.00
Assign From	HARMINDER KAUR	Assign Date	11/06/2024

2. Vehicle Details

Make & Model	TESLA MODEL Y (A)	C.C	-
Engine No.	-	Year of Reg.	09/05/2023
Chassis No.	LRWYHCFS2PC892733	Colour	METALLIC PEARL WHITE
Odometer	36893 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	255/35R21	PIRELLI	7
L/H Front Tyre	255/35R21	PIRELLI	7
R/H Rear Tyre	275/35R21	PIRELLI	5
L/H Rear Tyre	275/35R21	PIRELLI	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/05/2024	Inspection Date	12/06/2024
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days