

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG24070159/UNP3M4**Date:** 17/07/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30003440277
<b>Claimant Vehicle No :</b>	SMN1353Y	<b>Insured Vehicle No :</b>	SNC1681X
Date of Loss:	02/07/2024	Nature of Claim:	TP
		Claim No:	366136

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMN1353Y</b>	Engine No:	R16B25510580
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650KT000552
Reg. Date:	25/07/2019 (Man. Year: 2019)	Odometer:	70231 km
Colour:	Blue		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 ZR17	Rear Tyre Size:	225/45 ZR17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,164.24	1,330.32	1,833.92	57.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,320.00	560.00	29.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,044.24</b>	<b>2,650.32</b>	<b>2,393.92</b>	<b>47.46</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,044.24</b>	<b>2,100.00</b>	<b>2,944.24</b>	<b>58.37</b>

INSPECTION

Date of Assignment:	09/07/2024		
Date Inspected:	09/07/2024	Inspected At:	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2024)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN1353Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	683.60 FL	*617.30 FL
2	1		*REAR BUMPER PDC SENSOR	N/S Cracked	425.20 FL	*212.60 FL
3	1		*REAR BUMPER DIFUSSER	Deformed/Twisted	190.30 FL	*160.80 FL
4	2		*REAR BUMPER SIDE BRACKETS -R/L	Not Necessary	91.00 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINERS -R/L	Not Necessary	103.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	371.60 FL	*241.20 FL
7	1		*REAR BUMPER SIDE COVER -LH	Grazed	68.80 FL	*68.80 FL
8	1		*REAR BOOTLID	Repair	761.20 FL	*- FL
9	1		*REAR BOOT LOGO	Not Necessary	58.60 FL	*- FL
10	1		*REAR BOOT EMBLEM I-VTEC	Not Necessary	61.20 FL	*- FL
11	1		*REAR BOOT EMBLEM CIVIC	Not Necessary	61.20 FL	*- FL
12	1		*REAR BOOT W/STRIP	Not Necessary	161.20 FL	*- FL
13	1		*REAR END PANEL	Repair	457.20 FL	*- FL
14	1		*REAR TAILLAMP -LH	Cracked	411.20 FL	*324.70 FL
15	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
					Sub Total (S\$)	
					3,945.30	1,655.40
					- List Item Discount on L Items 20.00/20.00% (S\$)	
					781.06	325.08
					Total Parts (S\$)	
					3,164.24	1,330.32

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK REAR ELECTRICAL WIRING	New	40.00	20.00
2	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	80.00	50.00
3	TO TUFF KOTE	New	60.00	0.00
4	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	New	900.00	700.00
5	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	New	800.00	550.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,880.00</b>	<b>1,320.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >