

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24070161/AVP3E2
Date: 24/10/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002521267
Claimant Vehicle No :	SKW3289M	Insured Vehicle No :	FBT9915Y
Date of Loss:	06/07/2024	Nature of Claim:	TP
		Claim No:	366137

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW3289M	Engine No:	P520318328
Make & Model:	MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A)	Chassis No:	JM6BM42A8G0318993
Reg. Date:	26/10/2015 (Man. Year: 2015)	Odometer:	195928 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,601.44	1,038.00	1,563.44	60.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	980.00	670.00	40.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,251.44	2,018.00	2,233.44	52.53
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	4,251.44	1,600.00	2,651.44	62.37

INSPECTION

Date of Assignment:	09/07/2024	
Date Inspected:	12/07/2024	Inspected At: YSK Auto Workshop (HQ) 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71 Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2024)
Parts:	143	MAZDA 3 1.4 SEDAN 1.5L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW3289M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,074.80 FL	*1,074.80 FL
2	2		*REAR BUMPER SIDE HOLDER	Not Necessary	76.00 FL	*- FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	109.00 FL	*- FL
4	1		*REAR BUMPER TOW COVER	Repair	33.60 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Repair	537.30 FL	*- FL
6	1		*REAR BUMPER SENSOR (2PCS)	Damaged (1Pc Only)	370.40 FL	*185.20 FL
7	1		*REAR END PANEL	Repair	559.60 FL	*- FL
8	1		*REAR END PANEL TOP GARNISH	Not Necessary	185.00 FL	*- FL
9	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	143.60 FL	*- FL
10	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
11	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
12	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
Sub Total (\$\$)						3,219.30 1,290.00
- List Item Discount on L Items 20.00/20.00% (\$\$)						617.86 252.00
Total Parts (\$\$)						2,601.44 1,038.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	600.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	600.00	500.00
3	WIRING CHECK	New	50.00	0.00
4	TUFF COAT	New	150.00	30.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE AND REFIT UPHOLSTERY	New	150.00	0.00
Gross Labour Cost (\$)			1,650.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >