

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ECICS Limited  
10 Eunus Road 8, #09-04A Singapore Post Centre  
Singapore 408600

**Our File No:** CS/ICS24070162/EVP3M4**Date:** 02/08/2024REFERENCE

Insured/Claimant: SIM WEE LIM Policy No: MPC24A00055201  
Date of Loss: 05/07/2024 Nature of Claim: OD Claim No: DMPC2400842H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL9149R**  
Make & Model: HONDA SHUTTLE, 1.5 G CVT (A) Engine No: L15B5000055  
Reg. Date: 15/03/2017 (Man. Year: 2016) Chassis No: GK81100054  
Colour: White Odometer: 131709 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: S\$43,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>         | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                         | 6,603.30          | 4,878.40          | 1,724.90          | 26.12         |
| Miscellaneous Items           | 570.00            | 190.00            | 380.00            | 66.67         |
| Labour                        | 3,470.00          | 1,770.00          | 1,700.00          | 48.99         |
| Paintwork Labour              | 0.00              | 0.00              | 0.00              |               |
| Towing                        | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>      | <b>10,643.30</b>  | <b>6,838.40</b>   | <b>3,804.90</b>   | <b>35.75</b>  |
| <b>+ GST 9.00/9.00% (S\$)</b> | 957.90            | 615.46            | 342.44            | 35.75         |
| <b>Nett Amount (S\$)</b>      | <b>11,601.20</b>  | <b>7,453.86</b>   | <b>4,147.34</b>   | <b>35.75</b>  |

INSPECTION

Date of Assignment: 09/07/2024 Present Location: Accord Auto Services Pte Ltd (HQ)  
ACCORD AUTO SERVICES PTE LTD  
10 ANG MO KIO INDUSTRIAL PARK 2A  
Date Inspected: 09/07/2024 Inspected At: #03-11, AMK AUTO POINT  
SINGAPORE 568047  
Estimated Period of Repair: 6.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                               |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                               |
| Part Source:  | (Last Synchronised: 02 Aug 2024)                                                                                                                                             |                                                               |
| Parts:        | N/A                                                                                                                                                                          | HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                             |
| Print Code:   | (Unsubmitted, no print-code for SLL9149R)                                                                                                                                    |                                                               |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                               |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                               |

Recommended Parts

| No.              | Qty | Part No. | Particulars                                 | Condition     | Repairer's | Amount      |
|------------------|-----|----------|---------------------------------------------|---------------|------------|-------------|
| 1                | 1   |          | *FRONT BONNET<br>(WCP)                      | Dented        | 480.00 F   | *480.00 F   |
| 2                | 2   |          | *FRONT BONNET HINGE<br>(WCP)                | Not Necessary | 44.00 F    | *- F        |
| 3                | 1   |          | *FRONT HEADLAMP RH<br>(WCP)                 | Cut           | 1,250.00 F | *1,250.00 F |
| 4                | 1   |          | *FRONT HEADLAMP LOWER BRACKET RH<br>(WCP)   | Not Necessary | 28.00 F    | *- F        |
| 5                | 1   |          | *FRONT BUMPER<br>(WCP)                      | Broken        | 480.00 F   | *480.00 F   |
| 6                | 1   |          | *FRONT BUMPER SIDE RETAINER RH<br>(WCP)     | Broken        | 6.00 F     | *6.00 F     |
| 7                | 1   |          | *FRONT BUMPER LOWER GRILLE<br>(WCP)         | Not Necessary | 55.00 F    | *- F        |
| 8                | 1   |          | *FRONT FOGLAMP GARNISH RH<br>(WCP)          | Not Necessary | 20.00 F    | *- F        |
| 9                | 1   |          | *FRONT FENDER RH<br>(WCP)                   | Dented        | 120.00 F   | *120.00 F   |
| 10               | 1   |          | *FRONT FENDER INNER SHIELD RH<br>(WCP)      | Crushed       | 80.00 F    | *80.00 F    |
| 11               | 1   |          | *FRONT REINFORMCENT BAR<br>(WCP)            | Not Necessary | 170.00 F   | *- F        |
| 12               | 1   |          | *FRONT SHOCK ABSORBER RH<br>(WCP)           | Bent          | 200.00 F   | *200.00 F   |
| 13               | 1   |          | *FRONT KUNCKLE ARM RH<br>(WCP)              | Bent          | 180.00 F   | *180.00 F   |
| 14               | 1   |          | *FRONT LOWER ARM RH<br>(WCP)                | Bent          | 110.00 F   | *110.00 F   |
| 15               | 1   |          | *FRONT WHEEL BEARING RH<br>(WCP)            | Jammed        | 85.00 F    | *85.00 F    |
| 16               | 1   |          | *FRONT WHEEL BEARING HUB RH<br>(WCP)        | Bent          | 75.00 F    | *75.00 F    |
| 17               | 1   |          | *FRONT RAEK END RH<br>(WCP)                 | Not Necessary | 55.00 F    | *- F        |
| 18               | 1   |          | *FRONT TIE ROD END RH<br>(WCP)              | Not Necessary | 35.00 F    | *- F        |
| 19               | 1   |          | *FRONT TRIANGLE GLASS RH<br>(WCP)           | Broken        | 330.00 F   | *330.00 F   |
| 20               | 1   |          | *FRONT TRIANGLE GLASS MOULDING RH<br>(WCP)  | Necessary     | 50.00 F    | *50.00 F    |
| 21               | 1   |          | *FRONT WINDSCREEN<br>(WCP)                  | Broken        | 800.00 F   | *800.00 F   |
| 22               | 1   |          | *FRONT WINDSCREEN MOULDING<br>(WCP)         | Necessary     | 60.00 F    | *60.00 F    |
| 23               | 1   |          | *FRONT WINDSCRREN WIPER GARNISH RH<br>(WCP) | Not Necessary | 12.00 F    | *- F        |
| 24               | 1   |          | *FRONT DOOR RH<br>(WCP)                     | Repair        | 380.00 F   | *- F        |
| 25               | 2   |          | *FRONT DOOR HINGE RH<br>(WCP)               | Not Necessary | 60.00 F    | *- F        |
| 26               | 1   |          | *FRONT SPORT RIM RH<br>(LOCAL REPAIR)       | Cut           | 800.00 F   | *100.00 FS  |
| Supplementary #1 |     |          |                                             |               |            |             |
| 27               | 1   |          | *FRONT ANTI ROLL BAR LINKAGE<br>(WCP)       | Bent          | 38.00 F    | *38.00 F    |

Report was unsubmitted during this print-out.

| No.                                           | Qty | Part No. | Particulars | Condition | Repairer's | Amount   |
|-----------------------------------------------|-----|----------|-------------|-----------|------------|----------|
| F=Franchise part. S=SpcNett.                  |     |          |             |           |            |          |
| Sub Total (S\$)                               |     |          |             |           | 6,003.00   | 4,444.00 |
| + Margin on L,N Items 10.00/10.00% (S\$)      |     |          |             |           | 600.30     | 434.40   |
| Total Parts (S\$)                             |     |          |             |           | 6,603.30   | 4,878.40 |
| Report was unsubmitted during this print-out. |     |          |             |           |            |          |

## Recommended Miscellaneous Items

| No                         | Qty | Particulars                                         | Repairer's    | Amount        |
|----------------------------|-----|-----------------------------------------------------|---------------|---------------|
| <b>Miscellaneous Items</b> |     |                                                     |               |               |
| 1                          | 1   | <b>FRONT BUMPER CLIPS</b><br>Necessary              | 50.00         | 30.00         |
| 2                          | 2   | <b>FRONT FENDER INNER SHIELD CLIPS</b><br>Necessary | 100.00        | 20.00         |
| 3                          | 2   | <b>SEALANT</b><br>Necessary                         | 320.00        | 60.00         |
| 4                          | 1   | <b>TYRE</b><br>Torn (80%)                           | 100.00        | 80.00         |
| <b>Sub Total (\$\$)</b>    |     |                                                     | <b>570.00</b> | <b>190.00</b> |

## Recommended Labour

| No                              | Particulars                                                                                                  | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                              |          |                 |                 |
| 1                               | <b>SPRAY PAINT ON ALL AFFECTED AREA</b>                                                                      | New      | 1,200.00        | 800.00          |
| 2                               | <b>LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA</b> | New      | 1,200.00        | 600.00          |
| 3                               | <b>TO CHECK WIRING SYSTEM</b>                                                                                | New      | 100.00          | 30.00           |
| 4                               | <b>TO APPLY ANTI RUST TREATMENT</b>                                                                          | New      | 120.00          | 30.00           |
| 5                               | <b>TO REMOVE/REPLACE/REFIX FRONT TYRE &amp; RIM</b>                                                          | New      | 150.00          | 30.00           |
| 6                               | <b>TO REMOVE/REPLACE/REFIX RH UNDER CARRIAGE</b>                                                             | New      | 200.00          | 0.00            |
| 7                               | <b>TO CHECK &amp; ADJUST WHEEL ALIGNMENT</b>                                                                 | New      | 150.00          | 80.00           |
| 8                               | <b>TO REMOVE/REFIX/REPLACE FRONT WINDSCREEN &amp; FRONT TRIANGLE GLASS RH TO NEW &amp; ETC</b>               | New      | 350.00          | 200.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                              |          | <b>3,470.00</b> | <b>1,770.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >