

Accord Auto Services Pte Ltd (Co Reg No: 201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	05/07/2024
Policy No:	MPC24A00055201	Date of Loss:	
Vehicle Reg. No.:	SLL9149R	Driveable?	UNKNOWN
Driver Age/Info:		Party At Fault:	YES
TP Injury Involved?	NO	Third Party Involved?	
Insured/Claimant:	SIM WEE LIM		
Make/Model:	HONDA SHUTTLE, 1.5 (A)	Vehicle Reg. Date:	15/03/2017
Vehicle Colour:	WHITE	Chassis No:	GK81100054
Engine No:	L15B5000055		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

Present Location: ACCORD AUTO SERVICES PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	6,561.50
Miscellaneous Items	570.00
Labour	3,470.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	10,601.50
+ GST 9.00% (\$)	954.14
Nett Amount (\$)	11,555.64

This claim is handled by: ADMIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

reference

t Source:

(Last Synchronised: 08 Jul 2024)

Parts: N/A

HONDA SHUTTLE 1.5 (A) (Model not available in database)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLL9149R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET / <i>OP</i>	0.00	0.00	*480.00 F
2	2		*FRONT BONNET HINGE <i>X</i>	0.00	0.00	*44.00 F
3	1		*FRONT HEADLAMP RH <i>cut</i>	0.00	0.00	*1,250.00 F
4	1		*FRONT HEADLAMP LOWER BRACKET RH <i>?</i>	0.00	0.00	*28.00 F
5	1		*FRONT BUMPER <i>GR</i>	0.00	0.00	*480.00 F
6	1		*FRONT BUMPER SIDE RETAINER RH <i>GR</i>	0.00	0.00	*6.00 F
7	1		*FRONT BUMPER LOWER GRILLE <i>X</i>	0.00	0.00	*55.00 F
8	1		*FRONT FOGLAMP GARNISH RH <i>X</i>	0.00	0.00	*20.00 F
9	1		*FRONT FENDER RH <i>OP</i>	0.00	0.00	*120.00 F
10	1		*FRONT FENDER INNER SHIELD RH <i>CRH</i>	0.00	0.00	*80.00 F
11	1		*FRONT REINFORMCENT BAR <i>X</i>	0.00	0.00	*170.00 F
12	1		*FRONT SHOCK ABSORBER RH <i>?</i>	0.00	0.00	*200.00 F
13	1		*FRONT KUNCKLE ARM RH <i>?</i>	0.00	0.00	*180.00 F
14	1		*FRONT LOWER ARM RH <i>?</i>	0.00	0.00	*110.00 F
15	1		*FRONT WHEEL BEARING RH <i>?</i>	0.00	0.00	*85.00 F
16	1		*FRONT WHEEL BEARING HUB RH <i>?</i>	0.00	0.00	*75.00 F
17	1		*FRONT RAEK END RH <i>X</i>	0.00	0.00	*55.00 F
18	1		*FRONT TIE ROD END RH <i>X</i>	0.00	0.00	*35.00 F
19	1		*FRONT TRIANGLE GLASS RH <i>GR</i>	0.00	0.00	*330.00 F
20	1		*FRONT TRIANGLE GLASS MOULDING RH	0.00	0.00	*50.00 F
21	1		*FRONT WINDSCREEN <i>GR</i>	0.00	0.00	*800.00 F
22	1		*FRONT WINDSCREEN MOULDING <i>GR</i>	0.00	0.00	*60.00 F
23	1		*FRONT WINDSCRREN WIPER GARNISH RH	0.00	0.00	*12.00 F
24	1		*FRONT DOOR RH <i>X</i>	0.00	0.00	*380.00 F
25	2		*FRONT DOOR HINGE RH <i>X</i>	0.00	0.00	*60.00 F
26	1		*FRONT SPORT RIM RH <i>cut (non-galvanised)</i>	0.00	0.00	*800.00 F

F=Franchise part.

Sub Total (S\$)

5,965.00

+ Margin on L,N Items 10.00% (S\$)

596.50

Total Parts (S\$)

6,561.50

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Particulars	Amount
Miscellaneous Items		
1	FRONT BUMPER CLIPS / PR	30 50.00
2	FRONT FENDER INNER SHIELD CLIPS / PR	20 100.00
3	2 SEALANT (Workman) / PR	60 320.00
4	1 TYRE - TP (80% of New)	80 100.00
Sub Total (S\$)		570.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	SPRAY PAINT ON ALL AFFECTED AREA	New 800	1,200.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New 600	1,200.00
3	TO CHECK WIRING SYSTEM	New 30	100.00
4	TO APPLY ANTI RUST TREATMENT	New 30	120.00
5	TO REMOVE/REPLACE/REFIX FRONT TYRE & RIM	New 30	150.00
6	TO REMOVE/REPLACE/REFIX RH UNDER CARRIAGE	New ?	200.00
7	TO CHECK & ADJUST WHEEL ALIGNMENT	New 80	150.00
8	TO REMOVE/REFIX/REPLACE FRONT WINDSCREEN & FRONT TRIANGLE GLASS RH TO NEW & ETC	New 200	350.00
Gross Labour Cost (S\$)			3,470.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)

9/7/24, 5.17pm

OD- Not AIL

Exam - ?

P/P

M Bel sy

to 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: