

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMG 6420R

| | REPLACEMENT OF PARTS | | | | | | |
|-----|--------------------------|----------------------|------------------------|-------------------|--|--|--|
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) | | | |
| 1 | REAR BUMPER | TO REPAIR SEE LABOUR | \$570.90 | \$0.00 | | | |
| 1 | REAR BUMPER SIDE HOLDER | CRACKED | \$97.60 | \$97.60 | | | |
| 1 | TAILLAMP | CRACKED | \$387.90 | \$387.90 | | | |
| 1 | TAILLAMP PANEL | TO REPAIR SEE LABOUR | \$320.40 | \$0.00 | | | |
| 1 | TAILLAMP LOWER BRACKET | NOT NECESSARY | \$35.10 | \$0.00 | | | |
| 1 | REAR WINDSCREEN MOULDING | NECESSARY | \$185.20 | \$185.20 | | | |
| 1 | REAR FENDER | DISTORTED | \$972.40 | \$972.40 | | | |
| 1 | REAR FENDER INNER TRIM | CRUMPLED | \$356.40 | \$356.40 | | | |
| | LESS 25.00% DISCOUNT | | (\$731.48) | (\$499.88) | | | |
| | | | \$2,194.42 | \$1,499.62 | | | |

| | Special Nett | | | | | | | |
|-----|---------------------------------------|---------------|------------------------|-------------------|--|--|--|--|
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) | | | | |
| 1 | SET REAR BUMPER CLIPS (SN) | NOT NECESSARY | \$30.00 | \$0.00 | | | | |
| 1 | REAR FENDER SEALANT (SN) | NECESSARY | \$60.00 | \$60.00 | | | | |
| 1 | SET REAR FENDER INNER TRIM CLIPS (SN) | NECESSARY | \$30.00 | \$30.00 | | | | |
| 1 | REAR WINDSCREEN SEALANT (SN) | NECESSARY | \$60.00 | \$60.00 | | | | |
| | | \$180.00 | \$150.00 | | | | | |

| Labour | | | | | | |
|--|---------------|------------------------|-------------------|--|--|--|
| Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) | | | |
| PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND TAILLAMP PANEL | NOT NECESSARY | \$1,000.00 | \$600.00 | | | |
| SPRAY PAINTING TO AFFECTED AREA | | \$800.00 | \$500.00 | | | |
| WIRING CHECK | | \$50.00 | \$30.00 | | | |
| TO APPLY TUFF COAT | | \$150.00 | \$60.00 | | | |
| TO REMOVE UPHOLSTRY | | \$150.00 | \$50.00 | | | |
| TO REMOVE REVERSE SENSOR | | \$100.00 | \$0.00 | | | |
| TO REMOVE VIDEO RECORDER | | \$100.00 | \$50.00 | | | |
| TO REMOVE REAR WINDSCREEN | | \$180.00 | \$120.00 | | | |
| TO REMOVE FUEL TANK | | \$150.00 | \$60.00 | | | |
| | | \$2,680.00 | \$1,470.00 | | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| GRAND TOTAL | \$5,054.42 | \$3,119.62 | | |
|--|------------|------------|--|--|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | \$2,500.00 | | |
| Report Ref No: CS/SMO24070164/Avp3e2 | | | | |

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.