

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24070166/TNP3E2**Date:** 27/09/2024REFERENCE

Insured/Claimant:	STEPHEN MCNULTY	Policy No:	7220055041	
Date of Loss:	29/06/2024	Nature of Claim:	OD	Claim No: 0890923293SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF3268C	Engine No:	DEM034525
Make & Model:	AUDI A5, 2.0 SPORTBACK QUATTRO (A)	Chassis No:	WAUZZZF55MA062382
Reg. Date:	20/05/2022 (Man. Year: 2021)	Odometer:	36131 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$185,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,567.00	12,165.92	16,401.08	57.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,802.00	3,122.00	3,680.00	54.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	35,369.00	15,287.92	20,081.08	56.78
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	34,769.00	14,687.92	20,081.08	57.76
+ GST 9.00/9.00% (\$\$)	3,129.21	1,321.91	1,807.30	57.76
Nett Amount (\$\$)	37,898.21	16,009.83	21,888.38	57.76

INSPECTION

Date of Assignment:	09/07/2024	
Date Inspected:	12/07/2024	Inspected At: 281 Alexandra Road Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,802.00 FS	*2,241.60 FS
2	1		*FRONT BUMPER SECURING STRIP	Necessary	45.00 FS	*35.68 FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	245.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Deformed	329.00 FS	*262.80 FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	675.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	329.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE	Cut	169.00 FS	*135.20 FS
8	1		*FRONT BUMPER TRIM - RH	Missing	60.00 FS	*48.00 FS
9	1		*FRONT BUMPER TRIM - CENTER	Not Necessary	143.00 FS	*- FS
10	1		*RADIATOR GRILLE	Not Necessary	2,098.00 FS	*- FS
11	1		*FRONT PARKING AID SENSOR	Not Necessary	286.00 FS	*- FS
12	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	11.00 FS	*- FS
13	1		*FRONT LOCK CARRIER TOP BRACKET	Not Necessary	183.00 FS	*- FS
14	1		*FRONT REINFORCEMENT BEAM	Not Necessary	1,033.00 FS	*- FS
15	2		*FRONT LOCK CARRIER TOP BRACKET SUPPORT LH / RH	Not Necessary	74.00 FS	*- FS
16	1		*OUT TEMP SENSOR BRACKET	Not Necessary	30.00 FS	*- FS
17	1		*FRONT BUMPER GUIDE SECTION - RH	Deformed	46.00 FS	*36.32 FS
18	1		*LED HEADLIGHT - RH	Cut	9,204.00 FS	*7,363.20 FS
19	1		*LED HEADLIGHT SPACER - RH (3PCS)	Necessary	150.00 FS	*119.44 FS
20	1		*LIFT CYLINDER - RH	Not Necessary	239.00 FS	*- FS
21	1		*LIFT CYLINDER BRACKET - RH	Not Necessary	19.00 FS	*- FS
22	1		*LIFT CYLINDER HOSE	Not Necessary	118.00 FS	*- FS
23	1		*FRONT FENDER - RH	Bent	1,264.00 FS	*1,011.20 FS
24	1		*FRONT FENDER ATTACHMENT PARTS - RH	Not Necessary	61.00 FS	*- FS
25	1		*FRONT FENDER CLOSING ELEMENT - RH	Deformed	92.00 FS	*73.60 FS
26	1		*FRONT FENDER BRACKET - RH	Bent	73.00 FS	*58.40 FS
27	1		*FRONT FENDER BRACKET - RH	Not Necessary	56.00 FS	*- FS
28	1		*FRONT FENDER BRACE - RH	Bent	177.00 FS	*141.20 FS
29	1		*FRONT FENDER BRACKET - RH	Not Necessary	72.00 FS	*- FS
30	1		*FRONT HEADLIGHT TOP COVER	Deformed	55.00 FS	*43.44 FS
31	1		*FRONT FENDER LEDGE COVER - RH LONG	Not Necessary	20.00 FS	*- FS
32	1		*FRONT FENDER LEDGE COVER - RH SHORT	Deformed	45.00 FS	*35.36 FS
33	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	332.00 FS	*265.60 FS
34	1		*FRONT WHEEL SPOILER - RH	Deformed	92.00 FS	*73.12 FS
35	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	190.00 FS	*- FS
36	1		*BONNET	Not Necessary	3,538.00 FS	*- FS
37	1		*BONNET ATTACHMENT PARTS	Not Necessary	138.00 FS	*- FS
38	2		*BONNET HINGE - LH / RH	Not Necessary	1,020.00 FS	*- FS
39	1		*BONNET IMPACT PROTECTION	Not Necessary	36.00 FS	*- FS
40	2		*BONNET IMPACT PROTECTION - LH / RH	Not Necessary	72.00 FS	*- FS
41	1		*FRONT ALUMINIUM RIM - RH	Not Necessary	2,123.00 FS	*- FS
42	1		*FRONT ALUMINIUM RIM RUBBER VALVE - RH	Not Necessary	15.00 FS	*- FS
43	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
44	1		*SUNDRIES	Necessary	500.00 FS	*23.52 FS
45	1		*FRONT BUMPER AIR GUIDE - RH	Deformed	56.00 FS	*44.64 FS
46	1		*RHS FRONT FENDER CHROME TRIM (SUPPLEMENTARY)	Necessary	192.00 FS	*153.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **28,567.00** **12,165.92**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET	New	2,600.00	1,100.00
5	TO RENEW RHS FRONT RIM. TO CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			6,802.00	3,122.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >