



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO WD 5033D

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	RH SIDE MIRROR	DENTED/CRACKED	\$980.00	\$785.00
1	RH SIDE MIRROR STAND	TO REPAIR SEE LABOUR	\$480.00	\$0.00
	LESS 10.00% DISCOUNT		(\$146.00)	(\$78.50)
			\$1,314.00	\$706.50

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF RH SIDE MIRROR STAND		\$200.00	\$100.00
	CHECK WIRING SYSTEM		\$120.00	\$15.00
			\$320.00	\$115.00

GRAND TOTAL			\$1,634.00	\$821.50
-------------	--	--	------------	----------

	RECOMMENDED COST OF REPAIRS		\$821.50
--	-----------------------------	--	----------

Report Ref No: CS/SPF24070169/Knp3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$821.50-\$1,000

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.