



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF24070169/Knp3e2	
ACCIDENT CLAIMS SECTION		Date:	24/07/2024	
(SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB)		Code:	SPF	
1 HEMMANT ROAD SINGAPORE 438675				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 3164E	Veh. Inspected	WD 5033D	
Policy No.	-	Coverage	0	
Claim No.	ACS/105/009/2024/027 (CF)	Excess	\$0.00	
Assign From	LAI PENCHONG	Assign Date	09/07/2024	
2. Vehicle Details				
Make & Model	UD TRUCKS (M)	C.C	10836	
Engine No.	GH11758679	Year of Reg.	22/12/2021	
Chassis No.	JNCMBP0G9KU044182	Colour	WHITE/BLUE	
Odometer	81975 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: NIL			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	295/80R22.5 (D)	FIRENZA	9/3	
L/H Front Tyre	295/80R22.5 (D)	FIRENZA	9/3	
R/H Rear Tyre	295/80R22.5 (D/D)	FIRENZA	6/6/8/8	
L/H Rear Tyre	295/80R22.5 (D/D)	FIRENZA	6/6/8/8	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S WING MIRROR.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/07/2024	Inspection Date	10/07/2024	
Survey held at	AUTOEXCEL ENGINEERING PTE LTD 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days				