

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITAL INSURANCE LTD		Ref:	CS/FCI24070170/Uvp3	
	16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Date:	15/10/2024	
			Code:	FCI2	
1.					
	Insured Veh.	SH 6959C	Veh. Inspected	FBL 8420G	
	Policy No.	D-24101861MFCT	Coverage	0	
	Claim No.	D24005664MFCT	Excess	\$0.00	
	Assign From	BETTY	Assign Date	09/07/2024	
2. Vehicle Details					
	Make & Model	YAMAHA SUPER TENERE	C.C	1199	
	Engine No.	P404E002280	Year of Reg.	15/12/2014	
	Chassis No.	JYADP041000001033	Colour	GREY	
	Odometer	- KM	Steering	AFFECTED	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: NIL			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	110-80-19	BRIDGESTONE	5	
	L/H Front Tyre				
	R/H Rear Tyre	150/70ZR17	BRIDGESTONE	5	
	L/H Rear Tyre				
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
DAMAGES SEE DETAILS.					
5. General Information					
	Accident Date	26/06/2024	Inspection Date	09/07/2024	
	Survey held at	BAN HOCK HIN CO.PTE LTD - BLK 8 D CITY, SINGAPORE 533758	EFU SOUTH STREE	T 1, #04-28 JTC DEFU INDUSTRIAL	
5a. Remarks					
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					