



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref:	CS/FCI24070171/Avp3	
		Date:	09/07/2024	
		Code:	FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8780L	Veh. Inspected	SMM 450L	
Policy No.	D-24101861MFCT	Coverage	0	
Claim No.	D24005966MFCT	Excess	\$0.00	
Assign From	CAROLINE	Assign Date	09/07/2024	
2. Vehicle Details				
Make & Model	HONDA FIT	C.C	1317	
Engine No.	L13B3930373	Year of Reg.	14/06/2019	
Chassis No.	GK33415884	Colour	BLUE	
Odometer	125870 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	175/70 R14	YOKOHAMA	6	
L/H Front Tyre	175/70 R14	YOKOHAMA	6	
R/H Rear Tyre	175/70 R14	YOKOHAMA	6	
L/H Rear Tyre	175/70 R14	YOKOHAMA	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/07/2024	Inspection Date	09/07/2024	
Survey held at	AUTO UNITED SG PTE LTD 13 KAKI BUKIT ROAD 4, #03-29, BARTLEY BIZ CENTRE, SINGAPORE 417807			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 21 Working Days				