



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLB 4461Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER FASCIA	CRACKED	\$1,187.80	\$1,187.80
1	FRONT BUMPER LOGO	NECESSARY	\$115.50	\$115.50
1	FRONT O/S BUMPER SIDE GRILLE	CRACKED	\$140.72	\$140.72
1	O/S BUMPER SIDE GRILLE GARNISH	BENT	\$85.72	\$85.72
1	O/S SIDE GRILLE PARKING SENSOR	SERVICEABLE	\$285.50	\$0.00
1	O/S SIDE GRILLE TOP GARNISH	SERVICEABLE	\$81.55	\$0.00
1	O/S BUMPER PARKING SENSOR-OUT	SERVICEABLE	\$265.55	\$0.00
1	FRONT O/S BUMPER SIDE RETAINER	DISTORTED	\$187.00	\$187.00
1	O/S FRONT GRILLE	SERVICEABLE	\$359.60	\$0.00
1	O/S HEAD LAMP	BROKEN	\$2,650.20	\$2,650.20
1	O/S HEADLAMP PANEL	BUCKLED	\$161.85	\$161.85
1	O/S HEADLAMP BALLAST	SERVICEABLE	\$1,157.15	\$0.00
1	O/S HEADLAMP CONTROL MODULE	SERVICEABLE	\$365.10	\$0.00
1	BONNET	BENT	\$1,496.80	\$1,496.80
1	FRONT O/S FENDER	TO REPAIR SEE LABOUR	\$708.90	\$0.00
1	FRONT O/S FENDER INNER SHIELD	SERVICEABLE	\$165.10	\$0.00
1	FRONT BUMPER SPONGE (ADDITIONAL)	CRACKED	\$195.25	\$195.25
1	FRONT BUMPER REINFORCEMENT (ADDITIONAL)	BENT	\$940.20	\$940.20
1	FRONT W/S GLASS WASHER TANK (ADDITIONAL)	DENTED	\$290.15	\$290.15
1	FRONT O/S BUMPER INNER PARTS (ADDITIONAL)	CRACKED	\$295.10	\$295.10
	LESS 5.00% DISCOUNT		(\$556.74)	(\$387.31)
			\$10,578.00	\$7,358.98

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER RIVET (SN)	NECESSARY	\$30.00	\$30.00
			\$30.00	\$30.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM		\$180.00	\$20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY REPLACED PARTS		\$800.00	\$660.00
	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT O/S FENDER		\$700.00	\$500.00
			\$1,680.00	\$1,180.00
GRAND TOTAL			\$12,288.00	\$8,568.98
	RECOMMENDED COST OF REPAIRS			\$8,568.98
Report Ref No: CS/AGI24070175/Knp3e2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.