

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070179/RUA3Q2  
Date: 15/11/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549\_04  
Claimant Vehicle No : SMY4648U Insured Vehicle No : GBE7664M  
Date of Loss: 06/07/2024 Nature of Claim: TP Claim No: MFL2024D0008745

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMY4648U  
Make & Model: MERCEDES-BENZ CLA180, 1.6 (R18 BI) (A) Engine No: 27091030769261  
Reg. Date: 04/11/2015 (Man. Year: 2015) Chassis No: WDD1173422N272666  
Colour: Grey Odometer: 139033 km  
Engine Capacity: 1595 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,904.32	19,267.82	2,636.50	12.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	2,660.00	770.00	22.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,334.32	21,927.82	3,406.50	13.45
Approved Total (Overridden) (S\$)		16,000.00		
(S\$)	25,334.32	16,000.00	9,334.32	36.84
+ GST 9.00/9.00% (S\$)	2,280.09	1,440.00	840.09	36.84
Nett Amount (S\$)	27,614.41	17,440.00	10,174.41	36.84
+ Car Rental (8.0 x S\$120.00/day + 9.00% GST) (S\$)		1,046.40		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		130.80		
Nett Liability (S\$)		18,644.45		
Global Sum Settlement (S\$)		18,600.00		

INSPECTION

Date of Assignment: 10/07/2024  
Date Inspected: 10/07/2024 Inspected At: Mova Automotive Pte Ltd (FAN YOONG BRANCH)  
15 Fan Yoong Road, CNG Singapore Centre  
Singapore 629792  
Estimated Period of Repair: 6.0 days

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2024)
Parts:	143	MERCEDES-BENZ CLA180 1.6 (R18 BI) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY4648U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Cracked	1,260.00 FL	*1,260.00 FL
2	1		*FRONT GRILLE GARNISH COVER	Cracked	398.00 FL	*398.00 FL
3	1		*FRONT GRILLE EMBLEM	Cracked	246.00 FL	*246.00 FL
4	1		*FRONT GRILLE EMBLEM BASE	Cracked	195.00 FL	*195.00 FL
5	1		*FRONT BUMPER	Deformed	1,820.00 FL	*1,820.00 FL
6	1		*FRONT BUMPER REINFORCEMENT	Serviceable	1,230.00 FL	*- FL
7	1		*FRONT BUMPER INNER SPONGE	Cracked	246.00 FL	*246.00 FL
8	1		*FRONT BUMPER BASIC CARRIER	Cracked	322.00 FL	*322.00 FL
9	1		*FRONT BUMPER LOGO EMBLEM	Necessary	148.00 FL	*148.00 FL
10	1		*FRONT RADAR SENSOR	Serviceable	1,490.00 FL	*- FL
11	1		*FRT RADAR SENSOR SUPPORT HOLDER	Serviceable	165.00 FL	*- FL
12	1		*FRONT SUPPORT CARRIER ASSY	Cracked	1,460.00 FL	*1,460.00 FL
13	1		*FRT SUPPORT CARRIER SIDE BRACKET RH	Cracked	125.00 FL	*125.00 FL
14	1		*FRONT HEADLAMP ASSY RH	Cracked	2,870.00 FL	*2,870.00 FL
15	1		*REAR BUMPER	Deformed	1,720.00 FL	*1,720.00 FL
16	1		*REAR BUMPER LOWER COVER	Cracked	550.00 FL	*550.00 FL
17	1		*REAR BUMPER LOWER LIP (CHROME)	Cracked	426.00 FL	*426.00 FL
18	1		*REAR BUMPER BASIC CARRIER	Cracked	272.00 FL	*272.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	1,080.00 FL	*1,080.00 FL
20	1		*REAR BUMPER REVERSE SENSOR	Missing	295.00 FL	*295.00 FL
21	1		*REAR UNDER COVER	Cracked	395.00 FL	*395.00 FL
22	1		*FRONT SAFETY BELT LH	Activated	1,380.00 FL	*1,380.00 FL
23	1		*FRONT SAFETY BELT RH	Activated	1,380.00 FL	*1,380.00 FL
24	1		*REAR SAFETY BELT LH	Activated	1,160.00 FL	*1,160.00 FL
25	1		*REAR SAFETY BELT RH	Activated	1,160.00 FL	*1,160.00 FL
26	1		*AIR BAG ECU CONTROL UNIT	Activated	1,280.00 FL	*1,280.00 FL
27	1		*F/RH FENDER (NPA)	Repair	0.00 FL	*- FL
28	1		*R/BOOT LID (NPA)	Repair	0.00 FL	*- FL
29	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
30	1		*R/SAFETY BELT LOCK LH	Jammed	392.60 FL	*392.60 FL
31	1		*R/SAFETY BELT LOCK RH	Jammed	392.60 FL	*392.60 FL
32	1		*R/SAFETY BELT HOLDER BRACKET LH	Cracked	89.40 FL	*89.40 FL
33	1		*R/SAFETY BELT HOLDER BRACKET RH	Cracked	89.40 FL	*89.40 FL
34	1		*FRONT DEFLECTOR COVER RH	Cracked	167.80 FL	*167.80 FL
35	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*40.00 FS
36	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*40.00 FS
					Sub Total (\$\$)	24,324.80 21,399.80
					- List Item Discount on L Items 10.00/10.00% (\$\$)	2,420.48 2,131.98
					Total Parts (\$\$)	21,904.32 19,267.82

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ,REPLACE ,REFIX FRONT BUMPER DISTANCE SENSOR ,DISTANCE SENSOR WIRING HARNESS ,RADAR SENSOR ASSY & ETC TO EFFECT REPLACE FRONT BUMPER	New	100.00	80.00
2	TO REMOVE,REPLACE & REFIX REAR BUMPER REVERSE SENSOR,REAR BUMPER REVERSE SENSOR WIRING HARNESS & ETC TO EFFECT REPLACE OF REAR BUMPER	New	100.00	80.00
3	TO REMOVE, REPLACE REPAIR ,READJUST FRONT & REAR ACCIDENT AREAS SUCH AS FRONT FENDER RH ,FRONT BUMPER ,GRILLE ASSY FRT SUPPORT CARRIER ASSY ,REAR BUMPER ,REAR END PANEL,REAR BOOT LID & ETC ,BACK TO ORIGINAL CONDITIONS	New	900.00	850.00
4	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER,FRONT FENDER RH ,REAR BUMPER,REAR END PANEL,REAR BOOT LID & ETC	New	1,200.00	1,000.00
5	TO REMOVE & REPLACE FRONT SAFETY BELT LH & RH ,REAR SAFETY BELT LH /RH AIR BAG ECU & ETC	New	400.00	250.00
6	TO CALIBRATE & RADAR SENSOR PROGRAMMING & ETC	New	650.00	350.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,430.00</b>	<b>2,660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >