



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2505133

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 05/08/2025
Reference CD/CTI24070181/Dpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHB 6270S
Insured Veh. CB 7426M
Claim No. SNM24D203847
Policy No. DMB1SNW00010632304
Accident Date 04/07/2024
Inspection Date 11/07/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS CHINA TAIPING INSURANCE (S) PTE LTD	Ref:	CD/CTI24070181/Dpa3q2
3 ANSON ROAD #16-00	Date:	05/08/2025
SPRINGLEAF TOWER SINGAPORE 079909	Code:	CTI

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	CB 7426M	Veh. Inspected	SHB 6270S
Policy No.	DMB1SNW00010632304	Coverage	0
Claim No.	SNM24D203847	Excess	\$0.00
Assign From	CECILIA LEE	Assign Date	10/07/2024

2. Vehicle Details

Make & Model	TOYOTA PRIUS 5DR HATCHBACK (AUTO)	C.C	1798
Engine No.	2ZR2F58772	Year of Reg.	05/12/2019
Chassis No.	JTDKB3FU003089646	Colour	BLUE
Odometer	- KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	WESTLAKE	5
L/H Front Tyre	195/65R15	WESTLAKE	5
R/H Rear Tyre	195/65R15	WESTLAKE	5
L/H Rear Tyre	195/65R15	WESTLAKE	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/07/2024	Inspection Date	11/07/2024
Survey held at	59 LOYANG DRIVE LEVEL 4 ROOM 7 SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SHB 6270S

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR TRUNK LID COVER	BENT	\$1,577.24	\$1,577.24
1	REAR TRUNK LID LOCK	SERVICEABLE	\$641.06	\$0.00
1	REAR TRUNK LID LOCK COVER	NOT NECESSARY	\$129.80	\$0.00
1	REAR TRUNK LID LOCK SWITCH	NOT NECESSARY	\$468.90	\$0.00
1	REAR TRUNK LID COVER TRIM BOARD	NOT NECESSARY	\$303.10	\$0.00
1	REAR TRUNK LID RUBBER	SERVICEABLE	\$511.28	\$0.00
1	REAR TRUNK LID LAMP G5 (O/S)	CUT	\$891.52	\$891.52
1	REAR TRUNK LID GLASS BLACK COLOR	NOT NECESSARY	\$2,197.58	\$0.00
1	BOARD ASSY ,BACK DOOR TRIM	NOT NECESSARY	\$356.16	\$0.00
1	GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	MTG BROKEN	\$1,845.58	\$913.60
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	\$85.12	\$85.12
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	\$73.36	\$73.36
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	\$74.06	\$74.06
1	THIRD BRAKE LIGHT	BROKEN	\$552.58	\$552.58
1	REAR TRUNK LID STRIKER	TO REPAIR SEE LABOUR	\$138.18	\$0.00
2	REAR TRUNK LID HINGE (LH/RH) @\$265.30	NOT NECESSARY	\$530.60	\$0.00
2	REAR TRUNK LID ABSORBER (LH/RH) @\$402.50	NOT NECESSARY	\$805.00	\$0.00
2	REAR TRUNK LID ABSORBER BRACKET (LH/RH) @\$179.06	NOT NECESSARY	\$358.12	\$0.00
2	REAR TRUNK LID STOPPER (LH/RH) @\$118.72	NOT NECESSARY	\$237.44	\$0.00
1	SPOILER SUB-ASSY REAR	DISTORTED	\$1,335.18	\$1,335.18
1	REAR BUMPER	BROKEN	\$642.04	\$642.04
1	REAR BUMPER REINFORCEMENT	BROKEN	\$446.32	\$446.32
1	REAR BUMPER UNDER COVER	NOT NECESSARY	\$773.64	\$0.00
2	REAR BUMPER SIDE RETAINER @\$157.78	NOT NECESSARY	\$315.56	\$0.00
1	REAR BUMPER UNDER CENTRE COVER	NOT NECESSARY	\$773.64	\$0.00
1	REAR BUMPER TOWING COVER	BROKEN	\$115.78	\$115.78
1	REAR BUMPER CLIPS	NECESSARY	\$30.80	\$30.80
2	REAR BUMPER SIDE CLIP @\$35.00	NOT NECESSARY	\$70.00	\$0.00
1	ARM SUB-ASSY ,REAR BUMPER RH	NOT NECESSARY	\$195.44	\$0.00
1	REAR BUMPER UNDER SIDE COVER (RH)	NOT NECESSARY	\$324.80	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	RETAINER ,REAR BUMPER SIDE RH	NOT NECESSARY	\$132.72	\$0.00
2	RETAINER ,REAR BUMPER ,UPPER SIDE (LH/RH) @\$42.98	NOT NECESSARY	\$85.96	\$0.00
1	RETAINER ,REAR BUMPER ,SIDE ,LH	NOT NECESSARY	\$132.72	\$0.00
1	REAR BUMPER UNDER SIDE COVER (LH)	NOT NECESSARY	\$324.80	\$0.00
1	ARM SUB-ASSY ,REAR BUMPER ,LH	NOT NECESSARY	\$195.44	\$0.00
1	REAR BUMPER LOWER COVER GARNISH G5	BROKEN	\$963.63	\$963.63
2	REAR BUMPER REFLECTOR LH/RH @\$258.80	O/S CUT / N/S NOT NECESSARY	\$517.60	\$258.80
2	TAIL LAMP ASSY (UPPER) G5 @\$942.90	O/S BROKEN / N/S NOT NECESSARY	\$1,885.80	\$942.90
2	TAIL LAMP ASSY (LOWER) G5 @\$860.58	O/S BROKEN / N/S MTG BROKEN	\$1,721.16	\$1,721.16
2	TAIL LAMP QUARTER PANEL @\$302.40	NOT NECESSARY	\$604.80	\$0.00
1	REAR END PANEL GARNISH COVER	SERVICEABLE	\$138.90	\$0.00
2	TAIL LAMP SIDE COVER @\$358.40	NOT NECESSARY	\$716.80	\$0.00
1	REAR END PANEL	DENTED	\$842.94	\$842.94
1	REAR END PANEL GARNISH	SERVICEABLE	\$294.80	\$0.00
1	REAR SPARE TYRE PANEL	NOT NECESSARY	\$960.80	\$0.00
1	REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	NOT NECESSARY	\$668.90	\$0.00
1	REAR FIBER TOOL BOX TRIM	NOT NECESSARY	\$557.20	\$0.00
1	SPARE TYRE LOCK NUT	NOT NECESSARY	\$123.76	\$0.00
1	TAIL LAMP LOWER WIRE	NOT NECESSARY	\$868.80	\$0.00
1	REAR EXHAUST PIPE RH	NOT NECESSARY	\$1,628.76	\$0.00
1	REAR EXHAUST PIPE HANGER	NOT NECESSARY	\$56.98	\$0.00
1	REAR EXHAUST PIPE INSULATOR	NOT NECESSARY	\$440.44	\$0.00
1	REAR WINDSCREEN GLASS W/MOULDING	NOT NECESSARY	\$2,489.62	\$0.00
1	BONNET	DENTED	\$1,330.70	\$1,330.70
1	INSULATOR HOOD	NOT FITTED	\$557.34	\$0.00
1	INSULATOR CLIPS	NOT NECESSARY	\$5.04	\$0.00
1	BONNET RUBBER	SERVICEABLE	\$49.70	\$0.00
1	BONNET HINGE (RH) (O/S)	BENT	\$80.78	\$80.78
1	BONNET HINGE (LH)	BENT	\$80.78	\$80.78
1	BONNET LOCK	BENT	\$185.64	\$185.64
1	CATCH HOOD AUXILIARY HOOK	NOT NECESSARY	\$12.04	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	RADIATOR GRILLE	BROKEN	\$813.20	\$316.87
1	RADIATOR GRILLE EMBLEM	MTG BROKEN	\$123.20	\$123.20
1	RADIATOR GRILLE EMBLEM LOWER GARNISH	DISTORTED	\$268.30	\$268.30
1	FRONT BUMPER COVER G5	BROKEN	\$1,322.48	\$586.18
1	FRONT BUMPER REINFORCEMENT	BROKEN	\$974.96	\$716.60
2	FRONT BUMPER REINFORCEMENT ABSORBER LH/RH @\$161.98	O/S BENT / N/S NOT NECESSARY	\$323.96	\$161.98
2	FRONT BUMPER LOWER REINFORCEMENT BRACKET LH/RH @\$462.00	NOT NECESSARY	\$924.00	\$0.00
1	ABSORBER ,FRONT BUMPER ,LOWER REINFORCEMENT	NOT NECESSARY	\$178.78	\$0.00
1	FRONT BUMPER SPONGE	TORN	\$110.32	\$110.32
1	FRONT BUMPER LOWER GRILLE	MTG BROKEN	\$208.04	\$208.04
1	LAMP ASSY ,FOG, RH	NOT NECESSARY	\$1,288.00	\$0.00
1	LAMP ASSY ,FOG LH	NOT NECESSARY	\$1,288.00	\$0.00
1	FRONT NO PLATE GARNISH	BROKEN	\$138.60	\$138.60
1	FRONT BUMPER CLIPS	NECESSARY	\$30.80	\$30.80
2	FRONT BUMPER SIDE RETAINER LH/RH @\$107.80	MISSING	\$215.60	\$215.60
1	FRONT LOWER CROSSMEMBER	NOT NECESSARY	\$500.78	\$0.00
1	FRONT LOWER CROSSMEMBER GARNISH	NOT NECESSARY	\$481.30	\$0.00
1	FRONT UNDER COVER	NOT NECESSARY	\$253.12	\$0.00
1	FRONT BUMPER TOP GARNISH	NOT NECESSARY	\$315.56	\$0.00
2	FRONT BUMPER SIDE GARNISH LH/RH @\$216.90	NOT NECESSARY	\$433.80	\$0.00
2	COVER ,FRONT BUMPER HOLE LH/RH @\$39.73	SERVICEABLE	\$79.46	\$0.00
1	REINFORCEMENT FRONT BUMPER LOWER	NOT NECESSARY	\$330.54	\$0.00
2	BRACKET FRONT BUMPER EXTENSION MOUNTING @\$154.56	NOT NECESSARY	\$309.12	\$0.00
2	SUPPORT FR BUMPER LH/RH @\$114.38	NOT NECESSARY	\$228.76	\$0.00
2	BRACKET FRONT BUMPER SIDE LH/RH @\$115.22	NOT NECESSARY	\$230.44	\$0.00
2	FRONT CHASSIS MEMBER SIDE COVER LH/RH @\$196.50	NOT NECESSARY	\$393.00	\$0.00
2	UNIT ASSY ,HEADLAMP LH/RH (LED) @\$4837.00	MTG BROKEN	\$9,674.00	\$5,470.56
2	HEADLAMP ECU @\$2176.20	NOT NECESSARY	\$4,352.40	\$0.00
2	HEAD LAMP PANEL (LH/RH) @\$336.14	DENTED	\$672.28	\$480.20
1	TOP PANEL CENTRE	DENTED	\$510.97	\$364.98
2	TOP PANEL SIDE LH/RH @\$204.26	DENTED	\$408.52	\$408.52



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	BRACE PANEL	TO REPAIR SEE LABOUR	\$105.28	\$0.00
2	BRACKET ,HEADLAMP MOUNTING LH/RH @\$35.70	NOT NECESSARY	\$71.40	\$0.00
1	RADIATOR ASSY	BENT	\$2,578.52	\$1,841.80
1	COOLANT	NOT NECESSARY	\$45.00	\$0.00
1	RADIATOR FAN MOTOR ASSY	BROKEN	\$1,093.90	\$925.82
2	HORN @\$157.79	NOT NECESSARY	\$315.59	\$0.00
1	CONDENSER ASSY ,W/RECEIVER	BENT	\$1,871.24	\$1,336.60
1	FENDER SUB-ASSY ,FRONT RH	DENTED	\$1,323.42	\$1,111.93
1	FRONT FENDER SHIELD RH	NOT NECESSARY	\$277.90	\$0.00
1	FRONT FENDER SHIELD CLIP	NOT NECESSARY	\$20.86	\$0.00
1	FRONT FENDER HYBRID EMBLEM RH	NOT NECESSARY	\$121.10	\$0.00
1	BRACKET FRONT SIDE PANEL RH	NOT NECESSARY	\$62.30	\$0.00
1	EXTENSION FRONT FENDER RH	NOT NECESSARY	\$66.08	\$0.00
1	SEAL FRONT FENDER TO COWL SIDE RH	NOT NECESSARY	\$21.28	\$0.00
1	GUSSET FRONT FENDER APRON LOWER RH	NOT NECESSARY	\$48.86	\$0.00
1	EXTENSION FRONT FENDER APRON FRONT RH	NOT NECESSARY	\$32.48	\$0.00
1	FRONT APRON TO COWL SIDE ,LOWER FRT RH	NOT NECESSARY	\$115.22	\$0.00
	LESS 20.00 / 25.00% DISCOUNT		(\$14,201.59)	(\$6,990.46)
			\$56,806.36	\$20,971.37

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	\$64.40	\$64.40
1	FRONT FENDER ADVERTISEMENT LOGO RH (SN)	NECESSARY	\$140.00	\$140.00
1	REAR TRUNK LOWER W/S MOULDING (SN)	NOT NECESSARY	\$180.00	\$0.00
1	REAR LOWER W/S SEALANT (SN)	NECESSARY	\$46.00	\$46.00
1	REAR NO PLATE WITH TRIM COVER (SN)	SERVICEABLE	\$140.00	\$0.00
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	\$56.00	\$56.00
1	REAR TRUNK LID COMFORT & TEL NO STICKER (SN)	NECESSARY	\$84.00	\$84.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	\$189.98	\$189.98
1	FRONT NO PLATE (SN) }	BENT	\$35.00	\$45.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT NO PLATE TRIM COVER (SN) }	BENT	\$42.00	\$0.00
			\$977.38	\$625.38
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TRUNK LID STRIKER AND BRACE PANEL.	NOT NECESSARY	\$2,600.00	\$1,200.00
	SPRAY PAINTING CHARGE		\$2,200.00	\$1,000.00
	WIRING CHARGE		\$100.00	\$30.00
	TUFF KOTE		\$100.00	\$40.00
	TOWING CHARGE		\$80.00	\$0.00
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	NOT NECESSARY	\$150.00	\$80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS		\$120.00	\$80.00
	REMOVE/REFIX EXHAUST PIPE		\$80.00	\$0.00
	REMOVE/REFIX RADIATOR		\$90.00	\$50.00
	REMOVE/REFIX AIRCON & REFILL GAS		\$130.00	\$80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE		\$550.00	\$0.00
			\$6,200.00	\$2,560.00
GRAND TOTAL			\$63,983.74	\$24,156.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				\$21,500.00
Report Ref No: CD/CTI24070181/Dpa3q2				


ABT

ANG BRYAN TANI



DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S





PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S






PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S




PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S




PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S




PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S




PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S




PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S




PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S




PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S




PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S



PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 11 of 11)

PHOTOGRAPHS FOR VEHICLE NO. : SHB 6270S

